

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/005 DATE OF INSPECTION: May 19, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

3. Topsoil -

The majority of the snow has melted off the topsoil piles at the Skyline mine site. The topsoil piles at the loadout have a high concentration of grasses and no signs of erosion could be seen. The possibility exists that some of the topsoil piles on the property could eliminate the requirement of having straw bales as a control measure for erosion. The decision would have to be made jointly by the operator and a soil specialist at DOGM.

4a. Diversion -

Several of the diversions and culverts were re-graded and cleaned of sediment from the melting snows.

4b. Other Sediment Control Measures

The pump house next to the state road could have a change out of straw bales between the creek and pump house. Certain bales are starting to deteriorate due to the winter snow. Operator has committed to change out the bales.

7. Refuse Piles

The refuse pile was inspected and the drainage ditch could be partly re-graded in one area but careful not to dig into the toe of the hillside until ground becomes less saturated.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Coastal States Energy/Utah Fuel, Keith Zobell
Mailed to: Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM)
Filed to: Price Field Office
Date: May 21, 1993

Inspector's Signature and Number: Stephen J. Demczak #39
Stephen J. Demczak