



## State of Utah

### Department of Natural Resources

MICHAEL R. STYLER  
*Executive Director*

### Division of Oil, Gas & Mining

JOHN R. BAZA  
*Division Director*

JON M. HUNTSMAN, JR.  
*Governor*

GARY R. HERBERT  
*Lieutenant Governor*

#### Representatives Present During the Inspection:

OGM	Jim Smith	Environmental Scientist III
Company	Mark Reynolds	Resident Agent
BLM	Sue Berger	Mining Engineer Technician
OGM	Priscilla Burton	Environmental Scientist III
OGM	Daron R. Haddock	Environmental Manager
OGM	Wayne Western	Environmental Scientist III
OGM	Joe Helfrich	Environmental Scientist III
OGM	Dave Darby	Environmental Scientist III
OGM	Pete Hess	Environmental Scientist III
BLM	Steve Rigby	Mining Engineer

Permittee: **HIAWATHA COAL CO INC**

Operator: **HIAWATHA COAL CO INC**

Site: **HIAWATHA MINE COMPLEX**

Address: **PO BOX 1245, HUNTINGTON UT 84528**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

#### Current Acreages

12,177.00	<b>Total Permitted</b>
290.00	<b>Total Disturbed</b>
	<b>Phase I</b>
	<b>Phase II</b>
	<b>Phase III</b>

#### Mineral Ownership

- Federal  
 State  
 County  
 Fee  
 Other

#### Types of Operations

- Underground  
 Surface  
 Loadout  
 Processing  
 Reprocessing

#### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Division conducted a pre-Phase 1 bond release inspection (95.92 acres) as well as a quarterly complete inspection at the Hiawatha Mine complex on April 2 and April 8, 2008. The Permittee has submitted a application for Phase 1 to the Division (Task ID #2895) and the review of that application has generated nine deficiencies. The 2895 document has been returned to the Permittee as deficient. The areas being considered within the application are slurry pond 5, slurry pond 4 (refuse pile #2), a portion of the prep plant area, and borrow areas "A" (east of pond 5) and "F" (north side of Utah State highway 122).

Virtually all of the snowpack has melted at the lower elevations of the Complex adjacent to the town. The middle fork facilities were accessible; south fork was not.

The DOGM will conduct a site visit on February 15, 2008, as part of the mid term permit review process.

## Inspection Report

Permit Number:	C0070011
Inspection Type:	COMPLETE
Inspection Date:	Wednesday, April 02, 2008
Start Date/Time:	4/2/2008 10:00:00 AM
End Date/Time:	4/8/2008
Last Inspection:	Thursday, March 06, 2008

Inspector: **Pete Hess, Environmental Scientist III**

Weather: **Sunny; clear but cold in AM.**

InspectionID Report Number: **1604**

Accepted by: jhelfric

4/14/2008

Inspector's Signature:

Date Wednesday, April 09, 2008

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

### **3. Topsoil**

Replaced topsoil depths were checked in several locations on the reclaimed Slurry pond 5 area (SE slope and East slope).

#### **4.a Hydrologic Balance: Diversions**

The Permittee has tried to redefine the ditch along the east toe of the pond 5/5A. Soil conditions were too wet at the time, and the equipment operator had a difficult time in extracting the machine. When soil moisture conditions improve, the maintenance will be re-addressed.

#### **4.b Hydrologic Balance: Sediment Ponds and Impoundments**

Sediment ponds 004 and 005 were observed from the east slope of reclaimed slurry pond #5. Both contained water; the group discussed whether the Permittee will reclaim these or allow them to remain with a post mining land use change as stock / wildlife watering ponds. The depression area in slurry pond 5 (referred to as pond 5A), is being considered for storm water runoff collection and treatment for the Hiawatha town area. The Permittee is considering building a subdivision within the town limits. MSHA does not recognize pond 5A, only recognizing pond 5 (including the backfilled/reclaimed/resoiled area) as still having the impounding capacity sufficient to meet MSHA pond requirements. The Permittee must breach the impounding embankment on the east side of 5A, certify the work (P.E), and then notify MSHA such that they can confirm that the basin no longer meets the requirements of 30 CFR 77.216(a) and R645-301-533.600, 742.222 and 742.223. The group instructed the Permittee to properly notify the Division as to their intent for future use of the impoundment in a post-mining land use change application. The first quarter of 2008 impoundment inspections for ponds 004, 006, 007, and 008 were conducted on March 28, 2008. Ponds 009 and 011 located at the south fork facilities were noted as not inspectable due to snow depths. As noted this day, south fork remains inaccessible.

#### **4.d Hydrologic Balance: Water Monitoring**

The Permittee notified the Division on March 7, 2008 that the fourth quarter of 2007 surface and ground water monitoring data for the Hiawatha Mine Complex was in the OGM data base pipeline, and that same was acceptable for uploading.

### **7. Coal Mine Waste, Refuse Piles, Impoundments**

Refuse pile #1 has had the most recently placed volumes of coal waste from the Bear Canyon #4 Mine spread, leveled and compacted. Noncoal waste was not visible in the freshly spread material. The Permittee anticipates that the recovery of fines from the #1 slurry cell will be re-initiated during 2008.

### **8. Noncoal Waste**

No activity is occurring at the site relative to the disposal of derelict machinery. The Permittee anticipates that a scrapper will be mobilized onto the site shortly.

**12. Backfilling And Grading**

The regraded / resoiled coal mine waste areas (Slurry ponds 4 and 5) were inspected by the DOGM / BLM group. The areas were reclaimed between 1995 and 2001, and cover is re-establishing. The contours of the reshaped areas appear to meet approximate original contour requirements. One of the deficiencies aired within the Task 2895 review is that the Permittee has not provided "as-built" maps of the reclaimed areas.

**13. Revegetation**

The Permittee did not provide vegetation information as part of the Task ID # 2895 application. This is also listed as a deficiency.

**16.a Roads: Construction, Maintenance, Surfacing**

At least one road was identified on the East slope of slurry pond #5 which still needs to be reclaimed.

**21. Bonding and Insurance**

The Permittee was notified by the Division on December 21, 2007, February 21, 2008 and April 3, 2008 that adequate bond coverage for the Hiawatha Mine Complex in the amount of 3.7 million dollars must be posted by April 15, 2008. The Permittee has made arrangements through J.P. Morgan Chase to extend the letter of credit for the existing in place bond amount on the two previous dates noted. The current general liability insurance is in effect through March 3, 2009. Coverage amounts for the each occurrence and general liability categories are adequate. Coverage for damages incurred from the use of explosives is provided. The cancellation clause has been modified to meet the requirements of R645-301-890.300.