

GREG BELL Lieutenant Governor

State of Utah	
DEPARTMENT OF NATURAL RESOURCE	S

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representatives Present During the Inspection:			
OGM	Priscilla Burton		
Company	Charles Reynolds		

Inspection Report

Permit Number:	C0070011
Inspection Type:	TECHNICAL
Inspection Date:	Wednesday, July 15, 2020
Start Date/Time:	7/15/2020 1:00:00 PM
End Date/Time:	7/15/2020 2:00:00 PM
Last Inspection:	Tuesday, June 9, 2020

Inspector: Priscilla Burton,

Weather: sun 90 F

InspectionID Report Number: 6717

Accepted by:SCHRISTE 7/22/2020

Permitee:	HIAWATHA CO	AL CO INC			
Operator:	HIAWATHA COAL CO INC				
Site:	HIAWATHA MINE				
Address:	PO BOX 1240,	HUNTINGTON	UT 84528		
County:	CARBON				
Permit Type:	PERMANENT C	OAL PROGRAM	N		
Permit Status:	INACTIVE				

Current Acreages		Mineral Ownership	Types of Operations		
12,177.00	Total Permitted	✓ Federal	✓ Underground		
197.00	Total Disturbed	✓ State	Surface		
97.50	Phase I	County	Loadout		
93.27	Phase II	✓ Fee	Processing		
93.27	Phase III	Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

I discussed gun range activity and the potential for lead contamination at the upper rail yard with Mr. Reynolds and Jim Staley, the gun contractor. Lead will be added as a parameter to the sampling program at the upper rail yard cover soils during final reclamation.

Exhibit II-4A shows the upper rail yard borrow location.



Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.

 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not

 appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil	\checkmark		\checkmark	
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	o Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Page 3 of 3

3. Topsoil

The upper rail yard will be the source of 75,543 CY of borrow soil for reclamation of slurry pond #1 (MRP p. 2-38 and pp. 2-40-2-44) It is Reclamation Area 13 (RA 13). Lead is naturally occurring in all soils, but gun range activity could increase lead content in soil. Lead (PB2+) is not biodegraded and persists in the soil, where it may be taken up by plants*. In high concentrations, lead interferes with photosynthesis and may affect soil organisms.** Consequently, the MRP page 2-5 states that the effect of the gun range would be evaluated in 2020.

The gun range contract will expire December 31, 2020. Ordinarily 20 trainings a year with 8 - 10 people take place. Recently, COVID-19 has stopped trainings all together. Mr. Staley explained gun range practices to date:

1. Participants stand in the upper rail yard or on the access road above the upper rail yard.

2. Practice targets are placed outside the permit area 600 - 1,000 feet to the North East, at the base of a sandstone escarpment.

3. The bullets are lead with a copper sheath. The casings are brass or steel.

4. The bullets hit the target off the permit area and are fragmented or flattened on impact.

5. The casings land 10 - 15 feet away, in the upper rail yard.

During the inspection, many brass and steel casings were seen in the surface layer of soil. Plastic shot gun casings were also seen.

The MRP states that at final reclamation, the surface six inches (including coal fines and bullet casings) will be scraped aside and placed in the cut. The exposed soil will be sampled prior to its use as cover over mine waste (Chap. 2, p. 2-38).

During this inspection, it was agreed that no further sampling was required at this time, but that final reclamation sampling for the upper rail yard should include lead analysis. I will work with Mr. Reynolds to write an amendment to the reclamation plan that describes the required sampling, the additional parameter and analytical procedure, and the acceptable values for total lead in the cover soil.

*Mouna Fahr, et. al. 2013. Effect of Lead on Root Growth. Fontiers in Plant Science. June 6, 2013. https://www.frontiersin.org/articles/10.3389/fpls.2013.00175/full, accessed 7/202020

**European Commission DG ENV. E3. Heavy Metals in Waste, Final Report Project ENV.E.3/ETU/2000/0058 https://ec.europa.eu/environment/waste/studies/pdf/heavy_metalsreport.pdf, accessed 7/20/2020

