

1-17-89
7085

0014

John



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: January 4, 1989
11:30 a.m. to 12:45 p.m.

Permittee and/or Operators Name: California Portland Cement
Business Address: 695 South Rancho Avenue, Colton, CA 92324-0514
Mine Name: Hidden Valley Permit Number: INA/015/007
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): None
State Official(s): Henry Sauer and Bill Warmack
Partial: XX Complete: Date of Last Inspection: December 5, 1988
Weather Conditions: Cold and cloudy
Acreage: Permitted 960 Disturbed 7 Regraded 7 Seeded 7 Bonded 7
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	(X)
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: INA/015/007

DATE OF INSPECTION January 4, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS
2. SIGNS AND MARKERS
3. TOPSOIL
4. HYDROLOGIC BALANCE
 - a. STREAM CHANNEL DIVERSIONS
 - b. DIVERSIONS
 - c. SEDIMENT PONDS AND IMPOUNDMENTS
 - d. OTHER SEDIMENT CONTROL MEASURES
 - e. SURFACE AND GROUNDWATER MONITORING
 - f. EFFLUENT LIMITATIONS
5. EXPLOSIVES
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL
- d. COAL PROCESSING WASTE
8. NONCOAL WASTE
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES
10. SLIDES AND OTHER DAMAGE
11. CONTEMPORANEOUS RECLAMATION
12. BACKFILLING AND GRADING
13. REVEGETATION
14. SUBSIDENCE CONTROL
15. CESSATION OF OPERATIONS
16. ROADS
 - a. CONSTRUCTION
 - b. DRAINAGE CONTROLS
 - c. SURFACING
 - d. MAINTENANCE
17. OTHER TRANSPORTATION FACILITIES
18. SUPPORT FACILITIES UTILITY INSTALLATIONS

: Copy of this Report:

Mailed to: John Rains, CPC; Karla Knoop, JBR; Brian Smith, OSM

Given to: Joe Helfrich - DOGM

Inspectors Signature and Number: #32 Henry Lauer Date: Jan. 4, 1989

1/13/89

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: INA/015/007

DATE OF INSPECTION January 4, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

Snow from previous storms has remained on site (3-5 inches deep). Weather conditions were cold and cloudy. Cattle were noticed north of the main access road. Maintenance items mentioned below do not constitute UMC violations.

2. Signs & Markers - The mine I.D. sign has been partially pushed over. The bullet-riddled sign needs to be replaced.
- 4d. Other Sediment Controls - Silt fences are in place and are in good repair.
12. Backfilling and Grading - Surface cracks have formed on the east slope immediately below the terrace (bench) on the south end of the reclamation. Although these cracks are minor (5-10 feet long x 1 inch wide x 2 inches deep) they need to be monitored in the future.

The terrace (bench) mentioned above appears to catch some of the drainage from the adjacent cliffs. Some of this drainage is breaching the crest of the bench. To prevent this in the future, a berm should be constructed (by hand) on the crest of the terrace.

13. Revegetation The netting and underlying alfalfa mulch have been torn off the surface of the access road. The damage has occurred from the end of the pavement to the gate. The mulch and netting need to be reapplied as soon as it is practical.

There is evidence of heavy rabbit usage (feces) along the access road. This could potentially damage revegetation-establishment, and should be monitored in the future.

djh
AT43/9-11