



Permit No. ACT/015/009

Inspection Date 18 July 1991

Permittee/Operator Name Mountain Coal Company

Business Address P.O. Box 1378

City Price State Utah Zip 84501

Mine Trail Mountain #9 Surface Underground Other

County Emery State Utah

Company Official(s) Scott Jones

State Official(s) Jess Kelley

Time of inspection 12:00 a.m. p.m. to 3:00 a.m. p.m. Partial Complete

Date of last inspection 21 June 1991 Weather conditions Warm and cloudy

Acreage 1415 Permitted 8.8 Disturbed Regraded Seeded 8.8 Bonded

Enforcement Action None

inspection report

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS		YES	NO	N/A	COMMENTS
1. Permits	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	9. Protection of fish, wildlife, and related environmental values	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10. Slides and other damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	11. Contemporaneous reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Hydrologic balance					12. Backfilling and grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a Stream channel diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	14. Subsidence control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c Sediment ponds and impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	15. Cessation of operations	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d Other sediment control measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	16. Roads				
e Surface and groundwater monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	a Construction	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
f Effluent limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	b Drainage controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	c Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Development waste and spoil disposal	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	d Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
7. Coal processing waste	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	17. Other transportation facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	18. Support facilities and utility installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

WHITE—DOGMI YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 18 July 1991

Please number comments to correspond with topics on previous page.

1. PERMITS

-Permit ACT/015/009 valid from 3/7/90 to 3/7/95.

-Bond is surety bond in the amount of \$463,711. Bond is held with the United Pacific Insurance Company. Bond No. U-630513 valid from 3/3/81.

-Liability Insurance is held with Insurance Company of North America. Policy No. HDO-GO-969065-7 was taken out in 1/1/88 and goes for the life of the mine.

-SPCC (Spill Prevention, Control and Countermeasure) plan certified 3/1/90 by Dan Guy.

2. TOPSOIL

The topsoil stockpile near the main portal is in good condition. It is covered with a good vegetative cover of grass and some sweet clover.

4. HYDROLOGIC BALANCE

(a) Stream Channel Diversions--The main culvert is functioning well. The trash rack at its entrance is clean and in good repair. Creek flow is very low.

(b) Diversions--All diversions are in good condition except the main disturbed ditch at the east edge of the property. This ditch was blocked by sediment and debris in two places but was cleaned out during the inspection. Special attention must be paid to this ditch since it is such an important part of the runoff control system and since it is at the edge of the loading area and, hence, a particular maintenance problem.

Copy of report mailed to Dan Guy/Mountain Coal; Brian Smith/OSM

Copy of report given to Joe Helfrich/DOGM; Price Field Office/DOGM

Inspector's signature Jesse W. Kelley No. 34

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 18 July 1991

Please number comments to correspond with topics on previous page.

16. ROADS

(d) Maintenance--Dust levels were low during the inspection because of recent rains.

However, the dust suppression piping system at the eastern edge of the property
is in need of repair and maintenance in the form of pipe and sprinkler head
replacement and repair. This should be done immediately so that dust does not
become a problem.

Copy of report mailed to Dan Guy/Mountain Coal; Brian Smith/OSM

Copy of report given to Joe Helfrich/DOGM; Price Field Office/DOGM

Inspector's signature Jesse W. Kelley No. 34

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE