



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 MICHAEL R. STYLER
Executive Director
Division of Oil, Gas and Mining
 JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	C0150009
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, July 20, 2016
Start Date/Time:	7/20/2016 11:00:00 AM
End Date/Time:	7/20/2016 2:00:00 PM
Last Inspection:	Tuesday, June 14, 2016

Representatives Present During the Inspection:
OGM Keenan Storrar

Inspector: Keenan Storrar
 Weather: Sunny, 85 F
 InspectionID Report Number: 5584
 Accepted by: JHELFRIC
 7/21/2016

Permittee: **FOSSIL ROCK RESOURCES, LLC**
 Operator: **FOSSIL ROCK RESOURCES, LLC**
 Site: **FOSSIL ROCK MINE**
 Address: **225 North 5th Street, 9th Floor, CO 81501**
 County: **EMERY**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages	Mineral Ownership	Types of Operations										
<table border="1"> <tr> <td style="width: 100px;">3,564.83</td> <td>Total Permitted</td> </tr> <tr> <td>27.83</td> <td>Total Disturbed</td> </tr> <tr> <td></td> <td>Phase I</td> </tr> <tr> <td></td> <td>Phase II</td> </tr> <tr> <td></td> <td>Phase III</td> </tr> </table>	3,564.83	Total Permitted	27.83	Total Disturbed		Phase I		Phase II		Phase III	<input checked="" type="checkbox"/> Federal <input checked="" type="checkbox"/> State <input type="checkbox"/> County <input checked="" type="checkbox"/> Fee <input type="checkbox"/> Other	<input checked="" type="checkbox"/> Underground <input type="checkbox"/> Surface <input type="checkbox"/> Loadout <input type="checkbox"/> Processing <input type="checkbox"/> Reprocessing
3,564.83	Total Permitted											
27.83	Total Disturbed											
	Phase I											
	Phase II											
	Phase III											

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

I traveled to the main mine site first. The area had received a very heavy rain within the past 48 hours, so in addition to walking the site, I inspected the stream channel both up and down stream of the main bypass culvert. I then traveled to waste rock site where I spoke with Lee about the operations and followed up on items from the last inspection.

Inspector's Signature:

Date Thursday, July 21, 2016

Keenan Storrar,
 Inspector ID Number: 71



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

3. Topsoil

The operations at the waste rock site have not yet re-handled topsoil placed on the outslope of the lifts.

4.a Hydrologic Balance: Diversions

The bypass culverts at the main mine site were clear of obstructions (Photo 1). The main channel did not have water flowing above the mine site. Below the mine site, only mine water discharge from the Cottonwood mine was flowing out of the bypass culvert. It appeared a very large storm had passed over upper Cottonwood Canyon creek above the main mine site. Vegetation and organic material had been laid down and deposited within the undisturbed creek bed by runoff that was up to 10 feet wide and nearly 2 feet deep within the wetted perimeter (Photos 2 and 3). The mine site probably received rainfall from the event, however it was clear the main mine site had not received the same rainfall intensity as the upper canyon. This is because all the diversions were properly conveying runoff to the sediment pond and it was holding only a foot or two of standing water (Photo 4). The pond would have been holding much more water had the same event passed over the mine site.

At the waste rock site I spoke to Lee about Diversion Ditch DA. The plan is to leave the ditch in place as the pile is excavated in 10' lifts. The floor of the excavated pit is sloped to drain runoff to the south and it will be tied back into Ditch DA when the pit floor is at the same elevation of the ditch (Photo 5). This will prevent the pit from impounding water and will route runoff from the surrounding hillslopes around the pit and work areas.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

As stated previously, the pond at the mine site had only a foot or so of impounded water. The waste rock pond was dry (Photo 6).

6. Disposal of Excess Spoil, Fills, Benches

Subsoil is actively being recovered from the uppermost lift at the waste rock site. The subsoil is being relocated to the northern end of the subsoil stock pile. A berm has been installed around the newly placed subsoil (Photo 7).

16.a Roads: Construction, Maintenance, Surfacing

It appeared road base had been laid down on the waste rock site road (Photo 8).

ATTACHMENT A – Photos July 20, 2016 site visit



PHOTO 1

The inlet of mine site bypass culvert appeared to be clear of debris.
July 20, 2016



PHOTO 2

The wetted perimeter above the mine site is seen where the grass is lying down.
July 20, 2016



PHOTO 3

The wetted perimeter below the mine site is seen where the grass is lying down.
July 20, 2016



PHOTO 4

The mine site pond impounding less than two feet of water.
July 20, 2016

ATTACHMENT A – Photos July 20, 2016 site visit



PHOTO 5

Ditch DA is seen on the left and the bottom of the pit is on the right. They reach the same elevation a little past the bottom left of the photo.
July 20, 2016



PHOTO 6

The waste rock site pond is dry.
July 20, 2016



PHOTO 7

The stockpiled subsoil is bermed.
July 20, 2016



PHOTO 8

Road base has been applied to the waste rock road.
July 20, 2016