

Print Form

Submit by Email

Reset Form

# Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified by the cover letter. During a complete inspection an inspector will check and verify the information.

## GENERAL INFORMATION

Company Name	CONSOL Mining Company LLC	Mine Name	Emery Deep Mine
Permit Number	C/015/0015	Permit expiration Date	1/07/2016
Operator Name	CONSOL Mining Company LLC	Phone Number	+1 (724) 485-4267
Mailing Address	1000 CONSOL Energy Drive	Email	kerrygoodballet@consolenergy.com
City	Canonsburg		
State	PA	Zip Code	15317

## DOGM File Location or Annual Report Location

Excess Spoil Piles

- Required  
 Not Required

Refuse Piles

- Required  
 Not Required

See Appendix A-2, Quarterly Coal Refuse Inspections

Impoundments

- Required  
 Not Required

See Appendix A-1, Annual Impoundment inspections

Other:

## OPERATOR COMMENTS

Underground mining operations have been idle with no production since 12/17/10.

Appendix A-1, Annual Impoundment Inspections    Appendix A-2, Quarterly Coal Refuse inspections  
Appendix B-1, 4th East Dust Monitoring    Appendix B-2 Annual Subsidence Survey    Appendix B-2a, Monthly Subsidence Reports  
Appendix B-3 Bryant 14th West Flow    Appendix B-4, Emery Town Well Report  
Appendix D-1, 2010 Annual Report and final MSHA Mine Maps

## REVIEWER COMMENTS

- Met Requirements     Did Not meet Requirements

# COMMITMENTS AND CONDITIONS

The Permittee is responsible for ensuring annual technical commitments in the Mining and Reclamation Plan and conditions accepted with the permit are completed throughout the year. The Division has identified these commitments below and has provided space for you to report what you have done during the past year for each commitment. If additional written response is required, it should be filed as an attachment to this report.

## Title: CULTURAL RESOURCE PROTECTION

**Objective:** To monitor the five eligible cultural resource sites that could be damaged as a result of subsidence in the zero zero north area. Sites include: 42Em3964, 42Em3965, 42Em3969, and 42Em3974.

**Frequency:** Annually after undermining until the Division determines subsidence is no longer an impact.

**Status:** ongoing, Undermining has not occurred to date.

**Reports:** Annual

**Citation:** MRP, Confidential Binder, Chapter X, Part A, Page 1

### Operator Comments

No mining occurred under these sites. Underground mining operations have been idle with no production since 12/17/10.

Reviewer Comments  Met Requirements  Did Not Meet Requirements

## Title: CONTROL OF COAL FINES DEPOSITION

**Objective:** To prevent coal fines from accumulating on undisturbed soils.

**Frequency:** Annual inspection of three transects, three sample sites each for % coal, 5 live vegetative cover, and presence of cryptogammic cover and soil color. Include the name of the person collecting the data, soil color data, and cryptogram observation.

**Status:** Annual inspections should be ongoing during periods of production. The data could be more effectively displayed using an excel spreadsheet so that comparisons of the data and trends may be seen over time.

**Reports:** Annual report, build on the table provided in Chapter X-C, page 5, with the inclusion of a column for soil color.

**Citation:** MRP, Chapter X part C, page 5b.

### Operator Comments

Refer to Appendix B-1, 4th East Dust Monitoring. Underground mining operations have been idle with no production since 12/17/10.

Reviewer Comments  Met Requirements  Did Not Meet Requirements

**Title: INVESTIGATIVE STUDY INTO RECLAMATION PRACTICE**

**Objective:** To develop an enhanced reclamation plan, based on an evaluation of soil chemistry and vegetation establishment on previous reclaimed sites. (results located in Chapter 11, Appendix 1). This is a four-phase project. Phase I involves reporting on the investigation of past reclamation sites and practices at the mine. Phase II requires to lower the profile of pond 6 stockpiles, reseed and keep wildlife off piles; reclaim ponds 4 & 5, and pond 1 subsoil pile; adjust final reclamation plans to incorporate beneficial treatments observed such as disking in 1 T/ac straw mulch; modify the seed mix to include only salt tolerant species and allow for a higher percentage of shrubs and forbs; adjust the reference areas to eliminate duplication. Phase III requires that the applied techniques be evaluated qualitatively annually and quantitatively between the 4th and 6th year. These evaluations will be correlated to precipitation data. Phase IV requires the permittee to revise the MRP to include the best technology for final revegetation.

**Frequency:** Ongoing

**Status:** Phase I has been met.

**Reports:** Qualitative report annually, and quantitative report 4th and 6th year.

**Citation:** MRP, Chapter III, page 4a, and Chapter III, appendix 1

Operator Comments

CONSOL representatives met with DOGM & Consultants to discuss in 2011 to develop a plan to address compliance and a field meeting is scheduled for early in 2014

Reviewer Comments  Met Requirements  Did Not Meet Requirements



**Title: WASTE STOCKPILE MATERIAL**

**Objective:** To identify chemical characteristics of material as it is placed on the Temporary Coal mine Waste Stockpile. Sample and analyze waste for acid toxic parameters in accordance with R645-301-731.300.

**Frequency:** One sample/600 cu yds of coal mine waste brought to the temporary stockpile.

**Status:** Ongoing

**Reports:** Provide analysis in annual report.

**Citation:** MRP, Chapter II, page 10.

Operator Comments

No additional mine waste has been added in 2013. Underground mining operations have been idle with no production since 12/17/10..

Reviewer Comments  Met Requirements  Did Not Meet Requirements

**Title: SUBSIDENCE MONITORING- MONTHLY INSPECTIONS**

**Objective:** Inspect the area outlined on Plate V-5 as full extraction areas when pillar splitting begins.

**Frequency:** Monthly until there is no record of additional subsidence.

**Status:** Ongoing

**Reports:** Track in annual report to ensure compliance. Resubmittal of monthly reports is not necessary if the operator has already submitted them. Division engineer will review reports annually to ensure compliance.

**Citation:** MRP, Chapter V, Binder 1 of 3, Page 36

Operator Comments

Underground mining operations have been idle with no production since 12/17/10. Annual subsidence surveys were performed in 2013 (refer to Appendix B-2, Annual Subsidence Survey). Monthly subsidence reports of the 00 North subsidence area that was previously mitigated are underway and per DOGM email dated 10/12/13 copies of the monthly subsidence report are being emailed to DOGM and are compiled in the annual report at Appendix B-2a, Monthly Subsidence Reports.

Reviewer Comments  Met Requirements  Did Not Meet Requirements

**Title: SUBSIDENCE MONITORING- POINTS OVER PARTIAL PILLAR SECTIONS**

**Objective:** monitor points over partial pillar sections that have been resurveyed once and where no significant movement (<0.5') was found will be surveyed within one year. If this subsequent survey shows no significant movement from the original survey, the point will be surveyed again at one year intervals. Points over advancing sections need not be resurveyed unless there has been evidence that subsidence has taken place (caving).

**Frequency:** As needed

**Status:** Ongoing

**Reports:** Track in annual report to ensure compliance. Resubmittal of monthly reports is not necessary if the operator has already submitted them. Division engineer will review reports annually to ensure compliance.

**Citation:** MRP, Chapter V, binder 1 of 3, page 36.

Operator Comments

Refer to appendix B-2, 2012 Annual Subsidence Survey

Reviewer Comments  Met Requirements  Did Not Meet Requirements

**Title: SUBSIDENCE MONITORING- NEW POINTS**

**Objective:** Resurvey new monitoring points established over advancing sections such as mains and submains within one year after mining has been completed beneath the station. Include dates that points were established to track if the points have been resurveyed within a year after mining has been completed.

**Frequency:** As needed.

**Status:** Ongoing.

**Reports:** Track in annual report to ensure compliance. Resubmittal of monthly reports is not necessary if the operator has already submitted them. Division engineer will review reports annually to ensure compliance.

**Citation:** MRP, Chapter V, binder 1 of 3, page 36.

Operator Comments

N/A, Underground mining operations have been idle with no production since 12/17/10..

Reviewer Comments  Met Requirements  Did Not Meet Requirements



N/A, Underground mining operations have been idle with no production since 12/17/10..

Reviewer Comments  Met Requirements  Did Not Meet Requirements

**Title: SUBSIDENCE MONITORING- MITIGATION REPORT**

**Objective:** Provide, to the Division on an as-needed basis, a subsidence mitigation report that describes the surface mitigation projects and their status broken down by surface land owners.

**Frequency:** quarterly

**Status:** Ongoing

**Reports:** Track in annual report to ensure compliance. Resubmittal of monthly reports is not necessary if the operator has already submitted them. Division engineer will review reports annually to ensure compliance.

**Citation:** MRP, Chapter V, binder 1 of 3, page 37.

Operator Comments

Underground mining operations have been idle with no production since 12/17/10. Annual subsidence surveys were performed in 2013 (refer to Appendix B-2, Annual Subsidence Report).  
Monthly subsidence reports of the 00 North subsidence area that was previously mitigated are underway and per DOGM email dated 10/12/13 copies of the monthly subsidence report are being emailed to DOGM and are compiled in the annual report at Appendix B-2a, Monthly Subsidence Report.  
Monthly flow measurements of the dam breach panel 14th West ( Bryant -14th West) are being taken and data presented in Appendix B-3, Bryant 14th West Flow

Reviewer Comments  Met Requirements  Did Not Meet Requirements

**Title: SUBSIDENCE MONITORING- UPDATE PRE-SUBSIDENCE SURVEY**

**Objective:** Update the existing pre-subsidence survey and plates six months before full extraction and provide copies to the surface land owner, the Division and the water conservancy district.

**Frequency:** As needed, six months prior to full extraction.

**Status:** Ongoing

**Reports:** Track in annual report to ensure compliance. Resubmittal of monthly reports is not necessary if the operator has already submitted them. Division engineer will review reports annually to ensure compliance.

**Citation:** MRP, Chapter V, binder 1 of 3, page 37.

Operator Comments

Underground mining operations have been idle with no production since 12/17/10. No new pre-subsidence surveys required with idle underground mining operations

Reviewer Comments  Met Requirements

Did Not Meet Requirements

**Title: SUBSIDENCE MONITORING- RESURVEY NEW MONITORING POINTS**

**Objective:** Resurvey new monitoring points established over partial pillar sections within six months after final mining has taken place beneath them. Provide dates that points were established to track if the points have been resurveyed within six months after final mining.

**Frequency:** as needed

**Status:** Ongoing

**Reports:** Track in annual report to ensure compliance. Resubmittal of monthly reports is not necessary if the operator has already submitted them. Division engineer will review reports annually to ensure compliance.

**Citation:** MRP, Chapter V, binder 1 of 3, page 36.

Operator Comments

N/A for 2013, no new monitoring points established. Underground mining operations have been idle with no production since 12/17/10.

Reviewer Comments  Met Requirements

Did Not Meet Requirements

**Title: EMERY TOWN WELL MONITORING**

**Objective:** Consol commits to providing an annual report that evaluates the monitoring data collected from Emery Town Wells #1 and #2.

**Frequency:** Annually

**Status:** Ongoing

**Reports:** Annual Report

**Citation:** Chapter VI, page VI-56.

Operator Comments

Refer to Appendix B-4 for the Emery Town Well Update report dated 2/28/2014

Reviewer Comments  Did Not Meet Requirements  Met Requirements

**Title: MONITOR FIVE ELIGIBLE SITES IN THE ZERO ZERO NORTH AREA FOR IMPACTS FROM MINING**

**Objective:** To monitor eligible cultural resource sites that could be damaged as a result of subsidence. Sites include: 42Em3964, 42Em3965, 42Em3966, 42Em3969, 42Em3974.

**Frequency:** Annually after undermining until the Division determines subsidence is no longer an impact.

**Status:** Ongoing. Undermining was expected to occur in 2010.

**Reports:** Annual Report

**Citation:** MRP, Confidential, Chap. X, Part A. page1.

Operator Comments

These sites have not been undermined at this time

Reviewer Comments  Met Requirements  Did Not Meet Requirements

# FUTURE COMMITMENTS AND CONDITIONS

The following commitments are not required for the current annual report year, but will be required by the permittee in the future as indicated by the "status" field. These commitments are included for information only, and do not currently require action. If you feel that the commitment is no longer relevant or needs to be revised, please contact the Division.

**Title: SOIL SAMPLING AT 4TH EAST PORTAL**

**Objective:** Verify soil characteristics prior to final reclamation grading through sampling and analysis for pH, SAR, and EC with particular attention to those areas that were treated with dust suppressant.

**Frequency:** At final reclamation.

**Status:** At final reclamation.

**Reports:** report findings to Division.

**Citation:** MRP, Chapter III part C.1, page 11 and Appendix X, part C-3, page 24.

**Title: SOIL SAMPLING OF POND NO. 4 AND POND NO. 9**

**Objective:** To determine if evaporative salts have accumulated to a toxic level.

**Frequency:** at final reclamation

**Status:** at final reclamation.

**Reports:** report to the Division.

**Citation:** MRP, Chapter III, part C-1, page 12.

**Title: SOIL TESTING OF RECLAIMED SITE BEFORE SEEDING**

**Objective:** To verify the suitability of the growth media.

**Frequency:** At reclamation.

**Status:** At reclamation, before seeding.

**Reports:** report to Division.

**Citation:** MRP, Chapter VIII, part C-4, page 21, paragraph 1.

**Title: PERMANENT WASTE DISPOSAL SITE SUBSTITUTE TOPSOIL AND SUBSOIL COVER**

**Objective:** To determine how to segregate best available material within the disturbed area for use as substitute topsoil from less desirable material to be used as cover over the coal mine waste permanent disposal site.

**Frequency:** Prior to construction of permanent disposal site, Consol will resample the gravel pit site for topsoil substitute quality and quantity, and cover material quality. The site will be sampled on one sample per acre grid, with analysis on one foot

**Status:** Future Commitment

**Reports:** report to Division.

**Citation:** MRP, Chap VII, App. VII-2, pg. 2

**Title: IDENTIFY CHEMICAL CHARACTERISTICS OF COAL MINE WASTE PRIOR TO FINAL BURIAL OR TREATMENT**

**Objective:** In accordance with R645-301-731.300, determine chemical characteristics of coal mine waste in existing temporary coal mine waste stockpile. Commitment to core temporary pile in at least 5 locations and analyze waste in 5 ft. intervals for pH, EC, SAR, Acid Base Accounting, Se, B, and texture.

**Frequency:** One year prior to moving the waste

**Status:** Future Commitment

**Reports:** report to Division.

**Citation:** MRP, Chap III, pg. 13

**OPERATOR COMMENTS (OPTIONAL)**

**REVIEWER COMMENTS**

## REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

Reviewer Comments

# MAPS

Copies of mine maps, current and up-to-date, are to be provided to the Division as an attachment to this report in accordance with the requirements of R645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential.

Map Name	Map Number	Included		Confidential	
		Yes	No	Yes	No
Annual subsidence map		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Mine Map MSHA map and 2010 Annual Report Map		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Reviewer Comments  Met Requirements  Did Not Meet Requirements

**Appendix A-1**

Annual Impoundment Inspections



902-15

EarthFax

September 30, 2013

Tim Kirschbaum  
Environmental Engineer  
Consolidation Coal Company  
P.O. Box 566  
Sesser, IL 62884-0566

Subject: Emery Mine sedimentation pond annual inspection results

Dear Tim:

On September 18, 2013 I inspected the sedimentation ponds at the Emery Mine for the purpose of the 2013 annual inspection. The results of those inspections are attached.

It is my opinion that the ponds adequately serve their intended purpose and may continue to be used for that purpose. However, minor improvements should be made to the inlet of Pond 5 to minimize the potential for erosion at this inlet. Furthermore, fill material should be added to the roadway on the south side of Pond 9 to prevent draining of that pond onto the 4<sup>th</sup> East portal slope in the future. I have noted these issues on the inspection forms.

Other than the above issues, I did not observe any conditions associated with the ponds that require attention.


Please contact me if you have any questions.

Sincerely,

Richard B. White, P.E.  
President

Enclosure

Cc: John Gefferth (Civil & Environmental Consultants, Inc.)



*To enter text, click in the box and type your response. If a box already contains an entry select the entry and type the replacement. You can use the **tab** key to move from one field to the next. To select a check box, click in the box or type an x.*

**GENERAL INFORMATION**

Report Date	30 Sep 2013
Permit Number	ACT 015/015
Mine Name	Emery Mine
Company Name	Consolidated Coal Company

**IMPOUNDMENT IDENTIFICATION**

Impoundment Name	Pond 1
Impoundment Number	UPDES Outfall 001
UPDES Permit Number	UT0022616
MSHA ID Number	NA

**IMPOUNDMENT INSPECTION**

Inspection Date	18 Sep 2013
Inspected by	R.B. White
Reason for Inspection	Annual

(Annual, quarterly or other periodic inspections, critical installation , or completion of construction.)

- Describe any appearance of any instability, structural weakness, or any other hazardous condition.**

None

*Questions a and b are required for an impoundment, which functions as a Sedimentation pond.*

- a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Design sediment storage volume = 10.3 AF  
 60% sediment cleanout volume = 6.2 AF  
 Sediment cleanout elevation = 5935.7 ft

Average elevation of sediment in pond bottom = 5933.5 ft (based on Aug 2010 survey)

- b. Principle and emergency spillway elevations.

Spillway elevation = 5939.3 ft  
 With stop logs in place, the spillway elevation can be raised a minimum of an additional 12 inches.

**2. Field Information**

*Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.*

This pond serves as a location for the discharge of mine water, but has not been used for that purpose for several months. The pond was empty in September 2013. The embankments remain in good condition and the pond remains capable of serving its intended purpose if re-activated.

**3. Field Evaluation.**

*Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period*

The pond is capable of properly serving its intended function. Plenty of sediment capacity remains in the pond. The pond is adequate for continued use.

**QUALIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Richard J. Weller Date: 30 Sep 2013

**CERTIFIED REPORT**

**IMPOUNDMENT EVALUATION**

*If you answer NO to these questions, please explain under comments*

	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Is impoundment free of instability, structural weakness, or any other hazardous conditions?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**COMMENTS/ OTHER INFORMATION**

Consol has operated this pond in the past for the settlement of sediment contained in water that is discharged from the underground mine. Discharges to the pond ceased several months ago.

**CERTIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: Richard B. White, P.E. - President, EarthFax Engineering Group, LLC

*Full Name and Title*

Signature: Richard B. White Date 30 Sep 2013

P.E. Number & State 168246, UT

[ P.E. Cert. Stamp ]



*To enter text, click in the box and type your response. If a box already contains an entry select the entry and type the replacement. You can use the **tab** key to move from one field to the next. To select a check box, click in the box or type an x.*

**GENERAL INFORMATION**

Report Date 30 Sep 2013  
Permit Number ACT 015/015  
Mine Name Emery Mine  
Company Name Consolidated Coal Company

**IMPOUNDMENT IDENTIFICATION**

Impoundment Name Pond 2  
Impoundment Number UPDES Outfall 002  
UPDES Permit Number UT0022616  
MSHA ID Number NA

**IMPOUNDMENT INSPECTION**

Inspection Date 18 Sep 2013  
Inspected by R.B. White  
Reason for Inspection Annual

(Annual, quarterly or other periodic inspections, critical installation , or completion of construction.)

- 1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.**

None

*Questions a and b are required for an impoundment, which functions as a Sedimentation pond.*

- a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Design sediment storage volume = 0.83 AF  
 Design sediment storage elevation = 5905.3 ft  
 60% sediment cleanout volume = 0.50 AF  
 60% sediment cleanout elevation = 5903.0 ft

Approximate average current sediment storage elevation = 5900.4 ft

- b. Principle and emergency spillway elevations.

Spillway elevation = 5908.5 ft

**2. Field Information**

*Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on outslopes of embankments, etc.*

Water flows into this pond via a 12-inch diameter PVC pipe, which discharges onto riprap down the inside embankment. Approximately 2 to 3 inches of water and a small amount of accumulated sediment were in the pond at the time of the inspection. Large boulders have been placed downstream from the pond outlet. No signs of erosion were observed during the inspection. The dewatering culvert has been fitted with a skimmer. The pond appears to be in good, functional shape.

**3. Field Evaluation.**

*Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period*

No problems were observed.

**QUALIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Richard J. White Date: 30 Sep 2013

**CERTIFIED REPORT**

**IMPOUNDMENT EVALUATION**

*If you answer NO to these questions, please explain under comments*

- |  | YES                                 | NO                       |
|--|-------------------------------------|--------------------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan?   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions?                                 | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**COMMENTS/ OTHER INFORMATION**

The pond appears to be functioning as designed and is adequate for continued use.

**CERTIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: Richard B. White, P.E. - President, EarthFax Engineering Group, LLC

*Full Name and Title*

Signature: Richard B White Date 30 Sep 2013

P.E. Number & State 168246, UT

[ P.E. Cert. Stamp ]



*To enter text, click in the box and type your response. If a box already contains an entry select the entry and type the replacement. You can use the **tab** key to move from one field to the next. To select a check box, click in the box or type an x.*

**GENERAL INFORMATION**

Report Date	30 Sep 2013
Permit Number	ACT 015/015
Mine Name	Emery Mine
Company Name	Consolidated Coal Company

**IMPOUNDMENT IDENTIFICATION**

Impoundment Name	Pond 3
Impoundment Number	UPDES Outfall 005
UPDES Permit Number	UT0022616
MSHA ID Number	NA

**IMPOUNDMENT INSPECTION**

Inspection Date	18 Sep 2013
Inspected by	R.B. White
Reason for Inspection	Annual

(Annual, quarterly or other periodic inspections, critical installation , or completion of construction.)

- Describe any appearance of any instability, structural weakness, or any other hazardous condition.**

None

Questions a and b are required for an impoundment, which functions as a Sedimentation pond.

- a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Design sediment storage volume = 1.14 AF  
Design sediment storage elevation = 5906.5 ft  
60% sediment cleanout volume = 0.68 AF  
60% sediment cleanout elevation = 5905.0 ft  
  
Approximate average current sediment storage elevation = 5902.6 ft

- b. Principle and emergency spillway elevations.

Spillway elevation = 5907.8 ft

## 2. Field Information

*Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.*

The pond contained approximately 2 to 3 inches of water and some fresh sediment at the time of the inspection. The overflow consists of a 42-inch diameter riser with two 6-inch diameter side inlets (one with its invert located 15.5 inches below the top of the riser and the other with its invert 58 inches below the top of the riser). The riser outlet invert is located 69 inches below the top of the riser. There were no signs of recent water on the inside of the riser, indicating that the pond has not recently filled to this elevation. No signs of instability were observed, including on the steep, natural out slope on the north embankment.

**3. Field Evaluation.**

*Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period*

The pond appears to be functioning as designed.

**QUALIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Richard Fowler Date: 30 Sep 2013

**CERTIFIED REPORT**

**IMPOUNDMENT EVALUATION**

*If you answer NO to these questions, please explain under comments*

	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Is impoundment free of instability, structural weakness, or any other hazardous conditions?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**COMMENTS/ OTHER INFORMATION**

The pond appears to be functioning as designed and is adequate for continued use.

**CERTIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: Richard B. White, P.E. - President, EarthFax Engineering Group, LLC

*Full Name and Title*

Signature: Richard B. White Date 30 Sep 2013

P.E. Number & State 168246, UT

[ P.E. Cert. Stamp ]



*To enter text, click in the box and type your response. If a box already contains an entry select the entry and type the replacement. You can use the **tab** key to move from one field to the next. To select a check box, click in the box or type an x.*

**GENERAL INFORMATION**

Report Date	30 Sep 2013
Permit Number	ACT 015/015
Mine Name	Emery Mine
Company Name	Consolidated Coal Company

**IMPOUNDMENT IDENTIFICATION**

Impoundment Name	Pond 5
Impoundment Number	UPDES Outfall 007
UPDES Permit Number	UT0022616
MSHA ID Number	NA

**IMPOUNDMENT INSPECTION**

Inspection Date	18 Sep 2013
Inspected by	R.B. White
Reason for Inspection	Annual

(Annual, quarterly or other periodic inspections, critical installation , or completion of construction.)

**1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.**

The HDPE inlet culverts have been cut where they protrude from the interior pond slope to avoid future degradation of the material. A corrugated HDPE liner has been placed on this slope at the middle inlet to direct the flow of water into the pond. Riprap has been placed at the outlet from this liner to minimize erosion of the pond bottom at the inlet. Some of this riprap has been moved by the force of the water. Additional riprap should be placed along the liner edges and at the liner outlet to provide additional protection.

*Questions a and b are required for an impoundment, which functions as a Sedimentation pond.*

- a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Design sediment storage volume = 1.13 AF  
 Design sediment storage elevation = 5944.6 ft  
 60% sediment cleanout volume = 0.68 AF  
 60% sediment cleanout elevation = 5943.8 ft

Approximate average current sediment storage elevation = 5943.1 ft

- b. Principle and emergency spillway elevations.

Spillway elevation = 5949.2 ft

**2. Field Information**

*Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on outslopes of embankments, etc.*

This pond has four 24-inch diameter inlet culverts (one CMP and three HDPE). The pond contained 3.5 to 4 feet of water at the time of the inspection. Floatsam along the edge of the primary spillway indicated that the pond filled during recent storm events, but did not discharge. The open-channel outlet spillway shows no sign of erosion. The pond embankment shows no signs of instability.

**3. Field Evaluation.**

*Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period*

Some additional minor repairs should be implemented to the middle pond inlet, as described above, thereby further minimizing the potential for erosion of the pond in-slope. No stability or operational concerns were noted during the inspection.

**QUALIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Richard B. Lee Date: 30 Sep 2013

**CERTIFIED REPORT**

**IMPOUNDMENT EVALUATION**

*If you answer NO to these questions, please explain under comments*

	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Is impoundment free of instability, structural weakness, or any other hazardous conditions?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**COMMENTS/ OTHER INFORMATION**

The pond appears to be functioning as designed.

**CERTIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: Richard B. White, P.E. - President, EarthFax Engineering Group, LLC

*Full Name and Title*

Signature: Richard B White Date 30 Sep 2013

P.E. Number & State 168246, UT

[ P.E. Cert. Stamp ]



*To enter text, click in the box and type your response. If a box already contains an entry select the entry and type the replacement. You can use the **tab** key to move from one field to the next. To select a check box, click in the box or type an x.*

**GENERAL INFORMATION**

Report Date	<u>30 Sep 2013</u>
Permit Number	<u>ACT 015/015</u>
Mine Name	<u>Emery Mine</u>
Company Name	<u>Consolidated Coal Company</u>

**IMPOUNDMENT IDENTIFICATION**

Impoundment Name	<u>Pond 6</u>
Impoundment Number	<u>UPDES Outfall 003</u>
UPDES Permit Number	<u>UT0022616</u>
MSHA ID Number	<u>NA</u>

**IMPOUNDMENT INSPECTION**

Inspection Date	<u>18 Sep 2013</u>
Inspected by	<u>R.B. White</u>
Reason for Inspection	<u>Annual</u>

(Annual, quarterly or other periodic inspections, critical installation , or completion of construction.)

- Describe any appearance of any instability, structural weakness, or any other hazardous condition.**

It appears that the pond is operating as designed, with no instability concerns observed.

*Questions a and b are required for an impoundment, which functions as a Sedimentation pond.*

- a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Design sediment storage volume = 7.5 AF  
 60% sediment cleanout volume = 4.5 AF  
 Sediment cleanout elevation = 6012.5 ft

Average elevation of sediment in pond bottom = 6010.3 (based on August 2010 survey)

- b. Principle and emergency spillway elevations.

Spillway elevation = 6016.0 ft

**2. Field Information**

*Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on outslopes of embankments, etc.*

At the time of the inspection, the flow depth in the 6-inch Parshall flume at the pond outlet was 1.10 ft, representing a discharge of 2.40 cfs. The pond elevation was approximately 5 inches above the spillway invert at the time of the inspection.

**3. Field Evaluation.**

*Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period*

The pond appears to be operating as designed.

**QUALIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Richard B. White Date: 30 Sep 2013

**CERTIFIED REPORT**

**IMPOUNDMENT EVALUATION**

*If you answer NO to these questions, please explain under comments*

- |  | YES                                 | NO                       |
|--|-------------------------------------|--------------------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan?   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions?                                 | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**COMMENTS/ OTHER INFORMATION**

Consol operates this pond to settle sediment from mine discharge water.

**CERTIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: Richard B. White, P.E. - President, EarthFax Engineering Group, LLC

*Full Name and Title*

Signature: Richard B White Date 30 Sep 2013

P.E. Number & State 168246, UT

[ P.E. Cert. Stamp ]



*To enter text, click in the box and type your response. If a box already contains an entry select the entry and type the replacement. You can use the **tab** key to move from one field to the next. To select a check box, click in the box or type an x.*

**GENERAL INFORMATION**

Report Date	<u>30 Sep 2013</u>
Permit Number	<u>ACT 015/015</u>
Mine Name	<u>Emery Mine</u>
Company Name	<u>Consolidated Coal Company</u>

**IMPOUNDMENT IDENTIFICATION**

Impoundment Name	<u>Pond 8</u>
Impoundment Number	<u>UPDES Outfall 006</u>
UPDES Permit Number	<u>UT0022616</u>
MSHA ID Number	<u>NA</u>

**IMPOUNDMENT INSPECTION**

Inspection Date	<u>18 Sep 2013</u>
Inspected by	<u>R.B. White</u>
Reason for Inspection	<u>Annual</u>

(Annual, quarterly or other periodic inspections, critical installation , or completion of construction.)

**1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.**

The level of flow in Quitchupah Creek, adjacent to the pond, is occasionally high enough to nearly flow over the south embankment of Pond 8 and into the pond. Such a condition of near-overflow occurred within a few weeks of this inspection. Nonetheless, the embankment remains stable with no significant erosion of the outslope adjacent to the creek. No signs of instability were observed elsewhere within the pond.

*Questions a and b are required for an impoundment, which functions as a Sedimentation pond.*

- a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Design sediment storage volume = 2.00 AF  
 Design sediment storage elevation = 5910.0 ft  
 60% sediment cleanout volume = 1.35 AF  
 60% sediment cleanout elevation = 5909.0 ft  
 Approximate average current sediment storage elevation = 5907.0 ft

- b. Principle and emergency spillway elevations.

This impoundment is designed as a total containment pond without a spillway. The pond can contain the total design sediment volume plus the runoff from the 100-yr, 6-hr storm and still have a freeboard of 3.4 feet. The invert elevation on the dewatering pipe is set at 5910.0 ft.

**2. Field Information**

*Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on outslopes of embankments, etc.*

The pond inlets appear to be adequate. The pond contained approximately 4 to 6 inches of water at the time of the inspection. No substantial amount of sediment has accumulated in the pond.

**3. Field Evaluation.**

*Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period*

The pond appears to be operating as designed.

**QUALIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Richard Towler Date: 30 Sep 2013

**CERTIFIED REPORT**

**IMPOUNDMENT EVALUATION**

*If you answer NO to these questions, please explain under comments*

	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Is impoundment free of instability, structural weakness, or any other hazardous conditions?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**COMMENTS/ OTHER INFORMATION**

The pond appears to be functioning as designed and is adequate for continued use.

**CERTIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.


By: Richard B. White, P.E. - President, EarthFax Engineering Group, LLC

*Full Name and Title*

Signature: Richard B White Date 30 Sep 2013

P.E. Number & State 168246, UT

[ P.E. Cert. Stamp ]



To enter text, click in the box and type your response. If a box already contains an entry select the entry and type the replacement. You can use the **tab** key to move from one field to the next. To select a check box, click in the box or type an x.

**GENERAL INFORMATION**

Report Date	30 Sep 2013
Permit Number	ACT 015/015
Mine Name	Emery Mine
Company Name	Consolidated Coal Company

**IMPOUNDMENT IDENTIFICATION**

Impoundment Name	Pond 9
Impoundment Number	UPDES Outfall 009
UPDES Permit Number	UT0022616
MSHA ID Number	NA

**IMPOUNDMENT INSPECTION**

Inspection Date	18 Sep 2013
Inspected by	R.B. White
Reason for Inspection	Annual

(Annual, quarterly or other periodic inspections, critical installation , or completion of construction.)

- 1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.**

None

*Questions a and b are required for an impoundment, which functions as a Sedimentation pond.*

- a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Design sediment storage volume = 0.32 AF  
 Design sediment storage elevation = 6052.5 ft  
 60% sediment cleanout volume = 0.18 AF  
 60% sediment cleanout elevation = 6051.7 ft  
 Approximate average current sediment storage elevation = 6051.2 ft

- b. Principle and emergency spillway elevations.

Spillway elevation = 6054.6 ft

**2. Field Information**

*Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on outslopes of embankments, etc.*

A moderate amount of sediment has accumulated since the pond was last cleaned out. No signs of erosion were noted at the pond outlet or the spillway. No signs of instability were observed.

The pond contained approximately 1 foot of water at the time of the inspection. It appears that recent heavy thunderstorm activity filled the pond, causing some of the water to discharge down the ramp to the sealed 4<sup>th</sup> East portal. No water discharged from the pond spillway during this event (i.e., the roadway on the south side of the pond is slightly lower than the spillway elevation). Therefore, it is recommended that fill be added to the roadway on the south side of the pond to prevent water from draining to the portal slope in the future.

**3. Field Evaluation.**

*Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period*

No stability concerns were noted. As noted above, fill should be added to the roadway on the south side of the pond to prevent water from draining onto the 4<sup>th</sup> East portal slope in the future.

**QUALIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Richard B. Wheeler Date: 30 Sep 2013

**CERTIFIED REPORT**

**IMPOUNDMENT EVALUATION**

*If you answer NO to these questions, please explain under comments*

- |  | YES                                 | NO                       |
|--|-------------------------------------|--------------------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan?   | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions?                                 | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**COMMENTS/ OTHER INFORMATION**

The pond appears to be functioning as designed and is adequate for continued use.

**CERTIFICATION STATEMENT:**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.


By: Richard B. White, P.E. - President, EarthFax Engineering Group, LLC

*Full Name and Title*

Signature: Richard B. White Date 30 Sep 2013

P.E. Number & State 168246, UT

[ P.E. Cert. Stamp ]



## **Appendix A-2**

### Quarterly Coal Refuse Inspections

# INSPECTION FORM

## COAL REFUSE PILES AND COAL WASTE IMPOUNDMENTS

Name Quinn Healy Title PE

Date 2/4/13 Date last inspected 11/27/12

Site Name Emery Temp. Coal Stockpile Mine Name Emery

Refuse Facility ID # 1211-UT-09-00079-01

Refuse piles---Part A only  
 Impoundments---Part A and Part B

### Part A

- |  |   |     |     |    |
|--|---|-----|-----|----|
| 1. Foundation preparation (vegetation, topsoil removal?) | X | Yes | ___ | No |
| 2. Lift Thickness (inches)                               |   |     |     |    |
| 3. Compaction (4 to 6 complete passes)                   | X | Yes | ___ | No |
| 4. Burning* (specify extent and location)                |   | Yes | X   | No |
| 5. Angle of Slope (degrees)                              |   | 3:1 |     |    |
| 6. Seepage* (specify location, color, & appr. volume)    |   | Yes | X   | No |
| 7. Cracks or scarps* (location, size)                    |   | Yes | X   | No |
| 8. Major erosion problems* (location and extent)         |   | Yes | X   | No |
| 9. Water impounding against toe*                         |   | Yes | X   | No |

### Part B

- |   |  |     |     |    |
|---|--|-----|-----|----|
| 10. Embankment freeboard (feet)                     |  |     |     |    |
| 11. ___ Increase ___ Decrease in water level (feet) |  | Yes | ___ | No |
| 12. Sumps or sinkholes in slurry surface            |  | Yes | ___ | No |
| 13. Clogging* (pipes, ditches, spillway)            |  | Yes | ___ | No |
| 14. Trash racks clear and in place                  |  | Yes | ___ | No |

\* Adverse conditions noted in these items should be described (extent, location, volume, etc.) in the space provided. Major adverse changes could cause instability.

Inspection  
Category

Comments



I inspected the refuse pile on 2/4/2013.

The slopes are compacted and stable. The site drainage impoundment ditches are intact. There are no visible instabilities or other hazardous conditions.

# INSPECTION FORM

## COAL REFUSE PILES AND COAL WASTE IMPOUNDMENTS

Name Quinn Healy Title PE

Date 5/18/2013 Date last inspected 2/4/2013

Site Name Emery Temp. Coal Stockpile Mine Name Emery

Refuse Facility ID # 1211-UT-09-00079-01

Refuse piles---Part A only  
 Impoundments---Part A and Part B

### Part A

- |  |                                     |            |                                     |    |
|--|-------------------------------------|------------|-------------------------------------|----|
| 1. Foundation preparation (vegetation, topsoil removal?)---- | <input checked="" type="checkbox"/> | Yes        | <input type="checkbox"/>            | No |
| 2. Lift Thickness (inches)-----                              |                                     |            |                                     |    |
| 3. Compaction (4 to 6 complete passes)-----                  | <input checked="" type="checkbox"/> | Yes        | <input type="checkbox"/>            | No |
| 4. Burning* (specify extent and location)-----               |                                     | Yes        | <input checked="" type="checkbox"/> | No |
| 5. Angle of Slope (degrees)-----                             |                                     | <u>3:1</u> |                                     |    |
| 6. Seepage* (specify location, color, & appr. volume)-----   |                                     | Yes        | <input checked="" type="checkbox"/> | No |
| 7. Cracks or scarps* (location, size)-----                   |                                     | Yes        | <input checked="" type="checkbox"/> | No |
| 8. Major erosion problems* (location and extent)-----        |                                     | Yes        | <input checked="" type="checkbox"/> | No |
| 9. Water impounding against toe* -----                       |                                     | Yes        | <input checked="" type="checkbox"/> | No |

### Part B

- |  |  |     |                          |    |
|--|--|-----|--------------------------|----|
| 10. Embankment freeboard (feet)-----                                     |  |     |                          |    |
| 11. <u>    </u> Increase <u>    </u> Decrease in water level (feet)----- |  | Yes | <input type="checkbox"/> | No |
| 12. Sumps or sinkholes in slurry surface-----                            |  | Yes | <input type="checkbox"/> | No |
| 13. Clogging* (pipes, ditches, spillway)-----                            |  | Yes | <input type="checkbox"/> | No |
| 14. Trash racks clear and in place-----                                  |  | Yes | <input type="checkbox"/> | No |

\* Adverse conditions noted in these items should be described (extent, location, volume, etc.) in the space provided. Major adverse changes could cause instability.

Inspection  
Category

Comments



I inspected the refuse pile on 5/18/2013.

The slopes are compacted and stable. The site drainage impoundment ditches are intact. There are no visible instabilities or other hazardous conditions.

# INSPECTION FORM

## COAL REFUSE PILES AND COAL WASTE IMPOUNDMENTS

Name Quinn Healy Title PE

Date 8/13/2013 Date last inspected 5/8/2013

Site Name Emery Temp. Coal Stockpile Mine Name Emery

Refuse Facility ID # 1211-UT-09-00079-01

Refuse piles---Part A only  
 Impoundments---Part A and Part B

### Part A

- |  |   |     |     |      |
|--|---|-----|-----|------|
| 1. Foundation preparation (vegetation, topsoil removal?) | X | Yes |     | No   |
| 2. Lift Thickness (inches)                               |   |     |     |      |
| 3. Compaction (4 to 6 complete passes)                   | X | Yes |     | No   |
| 4. Burning* (specify extent and location)                |   | Yes |     | X No |
| 5. Angle of Slope (degrees)                              |   |     | 3:1 |      |
| 6. Seepage* (specify location, color, & appr. volume)    |   | Yes |     | X No |
| 7. Cracks or scarps* (location, size)                    |   | Yes |     | X No |
| 8. Major erosion problems* (location and extent)         |   | Yes |     | X No |
| 9. Water impounding against toe*                         |   | Yes |     | X No |

### Part B

- |   |  |     |  |    |
|---|--|-----|--|----|
| 10. Embankment freeboard (feet)                     |  |     |  |    |
| 11. ___ Increase ___ Decrease in water level (feet) |  | Yes |  | No |
| 12. Sumps or sinkholes in slurry surface            |  | Yes |  | No |
| 13. Clogging* (pipes, ditches, spillway)            |  | Yes |  | No |
| 14. Trash racks clear and in place                  |  | Yes |  | No |

\* Adverse conditions noted in these items should be described (extent, location, volume, etc.) in the space provided. Major adverse changes could cause instability.

Inspection  
Category

Comments



I inspected the refuse pile on 8/13/2013.  
 The slopes are compacted and stable. The site drainage impoundment ditches are intact. There are no visible instabilities or other hazardous conditions.

INSPECTION FORM

COAL REFUSE PILES AND COAL WASTE IMPOUNDMENTS

Name Quinn Healy Title PE

Date 11/24/2013 Date last inspected 8/13/2013

Site Name Emery Temp. Coal Stockpile Mine Name Emery

Refuse Facility ID # 1211-UT-09-00079-01

Refuse piles---Part A only
Impoundments---Part A and Part B

Part A

- 1. Foundation preparation (vegetation, topsoil removal?)--- X Yes \_\_\_ No
2. Lift Thickness (inches)--- X Yes \_\_\_ No
3. Compaction (4 to 6 complete passes)--- X Yes \_\_\_ No
4. Burning\* (specify extent and location)--- \_\_\_ Yes X No
5. Angle of Slope (degrees)--- 3:1
6. Seepage\* (specify location, color, & appr. volume)--- \_\_\_ Yes X No
7. Cracks or scarps\* (location, size)--- \_\_\_ Yes X No
8. Major erosion problems\* (location and extent)--- \_\_\_ Yes X No
Water impounding against toe\* --- \_\_\_ Yes X No


Part B

- 10. Embankment freeboard (feet)---
11. \_\_\_ Increase \_\_\_ Decrease in water level (feet)--- \_\_\_ Yes \_\_\_ No
12. Sumps or sinkholes in slurry surface--- \_\_\_ Yes \_\_\_ No
13. Clogging\* (pipes, ditches, spillway)--- \_\_\_ Yes \_\_\_ No
14. Trash racks clear and in place--- \_\_\_ Yes \_\_\_ No

\* Adverse conditions noted in these items should be described (extent, location, volume, etc.) in the space provided. Major adverse changes could cause instability.

Inspection Category

Comments



I inspected the refuse pile on 11/24/2013.

The slopes are compacted and stable. The site drainage impoundment ditches are intact. There are no visible instabilities or other hazardous conditions.

## **Appendix B-1**

4<sup>th</sup> East Dust monitoring data

**Consol Emery Mine - Coal Dust Plots 2013:** Observations made on May 29, 2013 by Karla Knoop (JBR Environmental Consultants, Inc.).

Site	Mixed Soil/Coal Cover (%)	Dominant Color of Soil/Coal Mixture	Bare Soil and/or Rock Cover (%)	Live Vegetative Cover (%)	Notes
1A	73	10YR 4/2	2	25	One small cryptogam. Good growth of galleta grass; a lot of halogeton. Dead wood and other litter. Recent trampling/ground disturbance from cows.
1B	60	10YR 5/3	10	30	No cryptogams observed. New grown on perennials; annuals sprouting. Not clear distinction between mixed soil and bare soil, grades from one to the other based on color; color noted is average color observed.
1C	18	10YR 6/3	80	2	Lichen growth; no cryptogams observed. More rock than soil.
2A	Plot destroyed during power line installation				
2B	60	10YR 6/3	15	25	1 cryptogams observed. Prickly pear has new growth, galleta and indian ricegrass doing well, mustard and globe mallow present. Soil color ranges; average reflected in column.
2C	50	10YR 6/4	45	3	No cryptogams observed. Robust vegetation; also halogeton. Litter also present. Not clear distinction between mixed soil and bare soil.
3A	Plot destroyed during power line installation				
3B	45	10YR 6/4	45	10	No cryptogams observed. Indian ricegrass, galleta, forbs, blooming mustard. Soil trampling by cattle. Not clear distinction between mixed soil and bare soil.
3C	90	10YR 5/4	7	3	One cryptogam observed. Indian ricegrass, galleta, prickly pear, other.

Note: Overall, vegetation looks much more robust than previous couple of years. Cattle have been in area and some plots were trampled and stakes knocked over.

**Appendix B-2**

Annual Subsidence Survey

**Consolidation Coal Co.  
November 2013 - Annual Subsidence Survey**

NAD 1983, Utah Central, US Survey feet  
NAVD 1988

**MEASURED POINTS**

POINT NAME	NORTHING	EASTING	PREVIOUS ELEVATION	Nov. 2007 ELEVATION	Nov. 2008 ELEVATION	Nov. 2009 ELEVATION	Dec. 2010 ELEVATION	Dec. 2011 ELEVATION	Dec. 2012 ELEVATION	Nov. 2013 ELEVATION	
			<b>ADJUSTED</b>								
			<b>OCT. 06 ELEV.</b>								
H-1	6758256.55	1713035.05	6082.81	6082.74	6082.88	6082.87	6082.94	6082.89	6082.87	6082.88	
36	6756805.63	1713716.02	6041.05	6040.79	6041.00	6040.89	6040.95	6040.91	6040.92	6040.92	
SMH	6755882.85	1712049.12	6057.67	6057.32	6057.61	6057.52	6057.59	6057.56	6057.54	6057.52	
90-1	6755171.22	1712000.26	6037.91	6037.45	6037.70	6037.63	6037.66	6037.69	6037.69	6037.67	
90-2	6755593.14	1712304.86	6053.83	6053.39	6053.64	6053.58	6053.63	6053.55	6053.56	6053.55	
35	6761558.54	1711229.20	6106.36	6106.67	6106.80		6106.92	6106.76	6106.77	6106.78	
83-1	6759093.54	1713116.69	6065.51	6065.46	6065.64	6065.58	6065.62	6065.60	6065.59	6065.59	
86-1	6757857.39	1706660.25	6003.40	6003.59	6003.84	6003.86	6003.93	6003.79	6003.77	6003.77	
86-2	6758652.96	1705551.95	6040.48	6040.76	6040.91	6040.93	6040.97	6040.76	6040.73	6040.72	
86-4	6760837.61	1702889.91	6078.44	6079.20	6079.40	6079.40	6079.42	6079.23	6079.24	6079.25	
86-5	6760155.85	1704278.88	6163.45	6163.97	6164.22	6164.21	6164.25	6164.10	6164.05	6164.07	
86-13	6759176.02	1704251.23	6036.06	6036.50	6036.65	6036.63	6036.68	6036.44	6036.41	6036.41	
88-2	6759134.95	1703887.62	6016.57	6017.01	6017.17	6017.18	6017.20	6016.95	6016.97	6016.95	
88-3	6758692.06	1704300.65	6014.34	6014.83	DESTROYED	DESTROYED	DESTROYED	DESTROYED	DESTROYED	DESTROYED	
88-4	6758006.11	1704828.28	5988.26	5988.56	5988.71	5988.73	5988.72	5988.51	5988.51	5988.52	
88-5	6757972.48	1705259.42	5994.61	5994.92	DESTROYED	DESTROYED	DESTROYED	DESTROYED	DESTROYED	DESTROYED	
88-6	6757177.64	1705879.38	5975.05	5975.24	5975.39	5975.42	5975.56	5975.48	5975.47	5975.48	
89-2	6762836.20	1705604.61	6200.08	6200.84	6200.98	6200.95	6201.03	6200.81	6200.76	6200.74	
89-3	6761091.78	1704846.48	6170.31	6170.90	6171.13	6171.11	6171.10	6171.16	6171.17	6171.18	
89-4	6762473.44	1706321.62	6184.86	6185.60	6185.69	6185.77	6185.81	6185.59	6185.52	6185.52	
90-03	6756435.50	1712926.84	6037.17	6036.93	6037.13	6037.04	6037.04	6037.12	6037.10	6037.10	
90-04	6757182.04	1713517.48	6031.02	6030.74	6030.89	6030.76	6030.89	6030.91	6030.89	6030.88	
90-4	6756652.76	1713321.91	6043.29	6043.02	6043.27	6043.16	6043.17	6043.20	6043.18	6043.19	
90-5	6757394.42	1713688.58	6036.66	6036.41	6036.56	6036.50	6036.55	6036.58	6036.55	6036.57	
90-6	6758779.41	1714726.46	6050.72	6050.62	6050.82	6050.78	6050.84	6050.88	6050.89	6050.91	
SM-C	6758743.87	1714106.30	6051.44	6051.38	6051.64	6051.53	6051.57	6051.54	6051.57	6051.61	
91-01	6756669.94	1712000.00	6052.23	6052.01	6052.25	6052.67	6052.20	6052.22	6052.19	6052.20	
91-02	6757585.42	1713036.14	6051.46	6051.28	6051.41	6051.38	6051.44	6051.42	6051.42	6051.40	
91-03	6758030.88	1713361.38	6055.63	6055.45	6055.56	6055.61	6055.62	6055.63	6055.63	6055.65	
91-04	6758791.86	1713935.17	6051.81	6051.72	6051.91	6051.82	6051.79	6051.81	6051.80	6051.79	
87-1	6757159.14	1706351.37	5990.51	5990.59	5990.78	5990.81	5990.90	5990.70	5990.70	5990.71	
97-1	6759589.84	1709488.21	6117.57	6117.83	6117.94	6117.97	6117.97	6117.95	6117.96	6117.98	
97-2	6758894.76	1709132.54	6116.53	6116.66	6116.84	6116.87	6116.87	6116.87	6116.88	6116.88	
E	6759462.66	1712234.87	6082.64	6082.75	6082.89	6082.95	6082.97	6082.94	6082.90	6082.91	
E1/4 28	6758451.40	1713666.32	6054.53	6054.45	6054.56	6054.52	6054.52	6054.53	6054.52	6054.56	
H-6	6758064.50	1711094.12	6095.91	6095.93	6096.06	6096.02	6096.04	6096.01	6096.01	6096.02	
W	6756275.89	1705674.96	5958.82	5958.80	5958.94	DESTROYED	DESTROYED	DESTROYED	DESTROYED	DESTROYED	
L	6754880.54	1705574.55	5950.19	5950.06	5950.29	5950.28	5950.21	5950.28	5950.24	5950.23	
N	6755536.21	1706165.54	5950.23	5950.16	5950.36	5950.39	5950.33	5950.36	5950.39	5950.41	
SMK-2	6758755.59	1710054.13	6102.92	6102.95	6103.12	6103.13	6103.13	6103.12	6103.13	6103.14	
SMK-3	6758965.95	1711660.45	6082.15	6082.18	6082.28	6082.27	6082.34	6082.32	6082.35	6082.36	
			<b>11-2006 ELEVATION</b>								
6-01	6761645.96	1710904.27	6110.04	6110.09	6110.27	6110.27	6110.33	6110.12	6110.13	6110.13	
6-02	6761002.37	1710059.15	6116.61	6116.60	6116.79	6116.88	6116.81	6116.57	6116.57	6116.58	
6-03	6760565.27	1709554.45	6117.32	6117.33	6117.55	6117.69	6117.57	6117.56	6117.52	6117.54	
6-04	6758380.42	1707028.80	6023.68	6023.77	6019.63	6019.51	6019.52	6019.35	6019.31	6019.34	
6-05	6758719.90	1706656.21	6030.59	6030.68	6027.85	6027.67	6027.58	6027.46	6027.41	6027.37	
6-06	6759875.49	1705933.25	6143.18	6142.91	6142.85	6142.71	6142.70	6142.56	6142.58	6142.56	
6-07	6760863.83	1706266.65	6170.20	6169.65	DESTROYED	DESTROYED	DESTROYED	DESTROYED	DESTROYED	DESTROYED	
6-08	6759343.46	1706993.37	6065.73	6065.23	6064.69	6064.36	6064.22	6063.99	6063.96	6064.00	
6-09	6760017.86	1706164.92	6141.75	6139.26	6139.27	6139.11	6139.04	6138.90	6138.88	6138.92	
6-10	6760383.96	1705795.14	6150.80	6148.22	6148.25	6148.13	6148.12	6147.98	6147.97	6147.97	
6-11	6759493.36	1715652.26	6056.86	6056.87	6057.03	6057.01	6057.04	6057.05	6057.05	6057.04	
6-12	6760098.03	1714699.42	6076.19	6076.15	6076.39	6076.35	6076.40	6076.37	6076.38	6076.38	
6-13	6760891.31	1713698.10	6090.16	6090.17	6090.36	6090.35	6090.33	6090.36	6090.35	6090.32	
6-14	6761793.53	1712734.97	6097.29	6097.30	6097.48	6097.43	6097.38	6097.40	6097.39	6097.38	
6-15	6762265.78	1712329.15	6107.03	6107.08	6107.19	DESTROYED	DESTROYED	DESTROYED	DESTROYED	DESTROYED	
6-16	6759657.74	1716089.80	6059.39	6059.44	6059.57	6059.56	6059.59	6059.61	6059.62	6059.66	
6-17	6761139.50	1717065.30	6071.56	6071.66	6069.61	6069.11	6068.97	6068.99	6068.97	6068.94	
6-18	6761947.48	1717858.85	6081.27	6081.34	6081.87	6081.54	6081.46	6081.49	6081.48	6081.48	
6-19	6762448.91	1718246.74	6085.90	6085.96	6086.59	6086.17	6086.11	6086.05	6086.01	6086.02	
6-20	6762741.05	1718538.73	6090.48	6090.52	6091.33	6090.73	6090.64	6090.57	6090.56	6090.60	
6-21	6760438.20	1716180.06	6070.28	6070.30	6070.97	6070.38	6070.50	6070.53	6070.53	6070.52	
6-22	6761333.56	1714916.16	6090.69	6090.68	6090.93	6090.92	6090.85	6090.92	6090.90	6090.89	
6-23	6762101.13	1714019.00	6111.33	6111.31	6111.58	6111.52	6111.45	6111.50	6111.49	6111.49	
6-24	6761067.04	1716301.20	6080.76	6080.80	6081.42	6079.91	6078.15	6078.22	6078.23	6078.24	
6-25	6762329.01	1714637.51	6106.02	6106.01	6106.23	6106.28	6106.13	6106.32	6106.30	6106.30	
6-27	6764041.79	1715533.49	6114.65	6114.65	6114.79	6114.81	6114.83	6114.85	6114.87	6114.86	
6-29	6762703.00	1712897.66	6141.81	6141.85	6142.02	6142.00	6141.99	6141.97	6141.96	6141.99	
6-30	6763349.98	1713654.71	6131.17	6131.20	6131.41	6131.32	6131.29	6131.31	6131.27	6131.24	
6-34	6760357.41	1706945.65	6148.20	6148.07	6148.20	6147.88	6147.83	6147.69	6147.67	6147.66	
86-11	6760330.48	1707019.83	6153.72	6153.62	6153.73	6153.39	6153.37	6153.20	6153.18	6153.21	
86-8	6762484.75	1713660.38	6125.27	6125.27	6125.43	6125.43	6125.43	6125.46	6125.45	6125.47	
R BOLT	6759584.85	1705565.44	6151.78	6151.79	6151.25	6151.17	6151.12	6150.97	6150.98	6151.00	
			<b>9-14-07 ELEVATION</b>								
07-01	6759689.65	1717605.56	6077.19	6077.17	6077.36	6077.32	6077.42	6077.45	6077.45	6077.48	
07-02	6761395.09	1718892.63	6080.35	6080.35	6080.54	6080.60	6080.58	6080.60	6080.59	6080.58	
07-03	6759677.37	1716935.01	6059.25	6059.28	6059.49	6059.43	6059.48	6059.53	6059.55	6059.60	
07-04	6760461.70	1717523.64	6067.06	6067.06	6067.20	6067.12	6067.22	6067.20	6067.19	6067.20	
07-05	6761257.03	1718095.27	6075.77	6075.80	6075.76	6075.70	6075.75	6075.73	6075.75	6075.77	
07-06											

**Appendix B-2a**  
**Monthly Subsidence**  
**Reports**

**EMERY MINE  
SUBSIDENCE INSPECTION REPORT**

This report summarizes the results of subsidence inspections conducted at the Emery Mine in Emery, Utah during the period of **September through November 2013**. The area of the observed subsidence is in the general vicinity of 38° 52' 58" North Latitude and 111° 13' 11" West Longitude over the northeastern portion of the 00 North panel.

**September 2013 Inspection**

An inspection was conducted on September 18, 2013 by Richard White (EarthFax Engineering Group) and Russel Jensen of Consol Energy. The purpose of this inspection was to update observations made during subsidence surveys conducted in December 2010 and January 2011 and evaluate the current status of efforts performed during the first quarter of 2011 to mitigate the surface impacts of subsidence in the area. These efforts involved regrading of the surface to cover cracks and smooth areas of abrupt changes in the ground surface.

During this inspection, six subsidence depressions were observed in the subject area. The coordinates of these depressions are provided in Table 1 and the locations relative to the 00 North panel are shown on Figure 1. These conditions are briefly described below. All depressions are located on land owned by Consol.

Depression #1

This depression covers an area of approximately 300 feet (North-South) by 150 feet (East-West). Subsidence cracks were observed primarily around the periphery of the depression. These cracks range up to a few inches in top wide and greater than 3 feet deep in some areas.

Depression #2

This depression measures approximately 120 feet (N-S) by 70 feet (E-W) and is located immediately south of Depression #1. Subsidence cracks were observed primarily around the periphery of the depression. These cracks range up to a few inches in top wide and greater than 3 feet deep in some areas.

Depression #3

This depression is located immediately west of Depression #1. It covers an area that measures about 300 feet (N-S) by 220 feet (E-W). Most of the observed cracks are on the west side of the depression. Most cracks are less than 1 foot deep, but a few exceed 3 feet in depth.

Depression #5

This depression is nearly circular, measuring about 180 feet (N-S) by 200 feet (E-W). Subsidence cracks were observed primarily around the periphery of the depression. These cracks range up to a few inches in top wide and greater than 3 feet deep in some areas.

## Depression #6

This depression is located between Depressions #2 and #5. It is approximately circular, measuring about 120 feet (N-S) by 100 feet (E-W). The depression contains a few cracks around the periphery, with one crack on the south side of the depression measuring more than 3 feet deep. Most of the other cracks are less than 1 foot deep.

### **October 2013 Inspection and Mitigation**

On October 10, 2013, wooden stake were placed at each depression for future reference. General observations of the area revealed no new cracks. On this and subsequent days through October 22, 2013, Mr. Jensen filled the majority of the subsidence cracks by hand and then graded the area with a wheel-mounted loader and backhoe. He then conducted a reconnaissance of the area and verified that all cracks had been filled.

### **November 2013 Inspection**

On November 5, 2013, Mr. Jensen conducted an inspection of the area with Karl Housekeeper, an inspector with the Utah Division of Oil, Gas and Mining. No new cracks were observed. Mr. Housekeeper stated that the area looked good and he would include an entry to this effect in his report.

On November 25, 2013 Mr. Jensen walked entire area of the 6 depressions over 00 North found no new cracks. He took photographs of the area, although the presence of snow made observations difficult.

### **Comparative Photographs**

Photographs of the six depressions are provided in Appendix A. Side-by-side photographs are taken from the same general locations, allowing comparisons to be made between inspection dates.

**TABLE 1**

Emery Mine Subsidence Depressions  
Location of Approximate Middle  
18 Sep 2013

Depression Number	Degree/Minute/Seconds		Decimal Degrees	
	Latitude	Longitude	Latitude	Longitude
1	38° 52' 59.0652"	111° 13' 08.4371"	38.88307°	111.21901°
2	38° 52' 56.4250"	111° 13' 08.8636"	38.88234°	111.21913°
3	38° 52' 58.9146"	111° 13' 11.2371"	38.88303°	111.21979°
4	38° 52' 59.8776"	111° 13' 13.7850"	38.88330	111.22050
5	38° 52' 58.0504"	111° 13' 12.3999"	38.88279	111.22011
6	38° 52' 56.4058"	111° 13' 11.1420"	38.88233	111.21976

Note: All areas of depression are located on land owned by Consol.




FIGURE 1. EMERY MINE SUBSIDENCE DEPRESSIONS



**ATTACHMENT A**

Comparative Photographs

**Depression #1 - September 2013**



**Depression #1 - October 2013**



**Depression #1 - November 2013**



Depression #1 - September 2013



Depression #1 - October 2013



Depression #1 - November 2013




Depression #2 - September 2013



Depression #2 - October 2013



Depression #2 - November 2013



Depression #2 - September 2013



Depression #2 - October 2013



Depression #2 - November 2013



Depression #3 - September 2013



Depression #3 - October 2013



Depression #3 - November 2013



Depression #3 - September 2013



Depression #3 - October 2013



Depression #3 - November 2013



Depression #4 - September 2013



Depression #4 - October 2013



Depression #4 - November 2013



Depression #4 - September 2013



Depression #4 - October 2013



Depression #4 - November 2013



Depression #5 - September 2013



Depression #5 - October 2013



Depression #5 - November 2013



Depression #5 - September 2013



Depression #5 - October 2013



Depression #5 - November 2013



Depression #6 - September 2013



Depression #6 - October 2013



Depression #6 - November 2013



Depression #6 - September 2013



Depression #6 - October 2013



Depression #6 - November 2013



**EMERY MINE  
SUBSIDENCE INSPECTION REPORT  
DECEMBER 2013**

In November 2013, Cody Ware of Ware Surveying and Engineering surveyed the established subsidence survey monuments at the Emery Mine in Emery County, Utah. A copy of his survey results is included in Attachment A. As indicated, elevation differences between the December 2012 survey and the November 2013 survey are essentially within survey method tolerances. Thus, no subsidence was measured by the survey.

On December 30, 2013, Russel Jensen of Consol Energy walked the area over the 00 North section of the Emery Mine. Subsidence cracks were documented in this area in September 2013 and mitigated in October 2013. No new subsidence cracks were observed. Mr. Jensen photographed all staked subsidence locations. Copies of these photographs are provided in Attachment B.

**ATTACHMENT A**

Subsidence Topographic Survey Results



**ATTACHMENT B**

Photographs of 00 North Subsidence Depressions  
December 30, 2013

Depression #1 - December 2013



Depression #2 - December 2013



Depression #3 - December 2013



Depression #4 - December 2013



Depression #5 - December 2013



Depression #6 - December 2013




## **Appendix B-3**

Bryant (14<sup>th</sup> West) flows

Consol Emery Mine  
 Panel 14th West  
 Bryant No. 1  
 Flow Measurements made at dam breach

Date	Flow (gpm)
6/13/2007	77
7/24/2007	52
8/28/2007	75
9/20/2007	69
10/19/2007	59
11/15/2007	54
12/17/2007	frozen
1/15/2008	Flowing under, over & through ice/snow; can't measure,
2/26/2008	67
3/21/2008	90
4/24/2008	35
5/22/2008	255
6/25/2008	230
7/16/2008	355
8/14/2008	275
9/10/2008	190
10/21/2008	117
11/19/2008	48
12/11/2008	56
1/21/2009	34
2/26/2009	23
3/10/2009	29
4/20/2009	12
5/13/2009	10
6/16/2009	235
7/27/2009	345
8/19/2009	265
9/18/2009	300
10/12/2009	60
11/5/2009	80
12/23/2009	58
1/28/2010	40
2/9/2010	Channel iced over, broke through to measure, but 20 results could be affected by remaining ice.
3/30/2010	10
4/20/2010	23
5/18/2010	150
6/15/2010	200
7/26/2010	235
8/26/2010	90
9/23/2010	96
10/26/2010	155
11/17/2010	83
12/1/2010	50
1/5/2011	frozen solid - no measurement
2/23/2011	49
3/30/2011	16
4/12/2011	10
5/17/2011	609
6/28/2011	700 This is an estimate; measurement compromised due to issues with equipment/high flows
7/19/2011	408
8/16/2011	301
9/13/2011	413
10/13/2011	408
11/16/2011	256
12/9/2011	153
1/30/2012	frozen - no measurement
2/22/2012	31
3/21/2012	23
4/18/2012	64
5/29/2012	114
6/26/2012	8.4
7/17/2012	29.4
8/14/2012	17
9/24/2012	4.3
10/18/2012	23.5
11/27/2012	33
12/18/2012	frozen - no measurement
1/10/2013	frozen - no measurement
2/21/2013	2
3/20/2013	1.4
4/16/2013	5.5
5/21/2013	2.7
6/28/2013	4.4
7/16/2013	4.1
8/6/2013	4.0
9/18/2013	16
10/22/2013	6.3
11/6/2013	25 estimate
12/10/2013	28 frozen but able to chop through for measurement w/ flume



**Appendix B-4**

Emery Town Well Report



EarthFax

February 28, 2014

Kerry Goodballet, P.E.  
Director of Permitting - Coal  
Consolidation Coal Company  
1000 Consol Energy Drive  
Canonsburg, PA 15317

Subject: Emery Town Well Data Update

Dear Kerry:

Attached is a summary of the data collected from the Emery Town wells from November 2007 through December 2013. Explanatory notes are provided at the bottom of the spreadsheet to assist in data interpretation.

The water-quality data collected from Well #1 during 2013 are consistent with data collected earlier from this location. However, the water-level data collected from Well #2 suggest that water levels dropped abruptly by about 15 feet between November 2012 and March 2013, remaining essentially constant since then. Russel Jensen, the individual at the mine responsible for data collection, indicated that the mine purchased a new water-level indicator in early 2013 and that he began using that probe beginning with the March 2013 monitoring event. To determine whether or not the change in probes could result in the apparent water-level discrepancy, I visited the Emery Town wells with Mr. Jensen on February 11, 2014. I independently measured the depth to water in Well #2 using the old Emery probe, the new Emery probe, and a probe owned by EarthFax Engineering. Both the new Emery probe and the EarthFax probe indicated that the depth to water was 243.2 feet. The old Emery probe did not respond until it was well below the water level. That probe then continued to respond even after it was removed from the well. Therefore, the old Emery probe is obviously faulty and probably has been for some time.

Given these observations, it is my opinion that the water levels reported for 2013 in Well #2 are correct and that levels has remained relatively constant since measurements began. It is further my opinion that previous mining activity at the Emery Mine has not adversely affected water levels or water quality at the Emery Town wells.

Please let me know if you have any questions regarding this matter.

Sincerely,

Richard B. White, P.E.  
President


Enclosure

cc: John Gefferth (Civil & Environmental Consultants, Inc.)






# Emery Town Well #2 Water Level Data



**Appendix D-1**

2010 Annual Report

and MSHA Maps



<ul style="list-style-type: none"> <li><span style="color: green;">—</span> Incline Airway</li> <li><span style="color: red;">—</span> Return Airway</li> <li><span style="color: blue;">—</span> Regular</li> <li><span style="color: purple;">—</span> Stopping</li> <li><span style="color: yellow;">—</span> Mandrel</li> <li><span style="color: cyan;">—</span> Attock</li> <li><span style="color: magenta;">—</span> Overcast</li> <li><span style="color: black;">—</span> Seal</li> <li><span style="color: black;">—</span> Curtain</li> <li><span style="color: black;">—</span> Roof Fall</li> <li><span style="color: black;">—</span> Primary Escarpment</li> <li><span style="color: black;">—</span> Secondary Escarpment</li> <li><span style="color: black;">—</span> Permit Area Boundary</li> <li><span style="color: black;">—</span> Floor Elevation</li> <li><span style="color: black;">—</span> Pool Elevation</li> <li><span style="color: black;">—</span> D/E Hole</li> <li><span style="color: black;">—</span> Control Point</li> <li><span style="color: black;">—</span> Bottom of Coal Elevation</li> <li><span style="color: blue;">—</span> Body of Water</li> <li><span style="color: green;">—</span> Refuge Alternative</li> <li><span style="color: green;">—</span> Surface Water</li> </ul>	<p style="text-align: center;">N</p> <p style="font-size: small;">There are no mines above or below and no oil or gas wells.</p>
<p><b>CONSOL ENERGY</b> CONSOLIDATION COAL COMPANY</p> <p><b>MSHA 1200 Map</b> (After Mine Closure)</p> <p>DRAWN BY: PRB      DATE: 9-10-2012</p> <p>SCALE: 1"=500'</p>	
<p>I hereby certify that to the best of my knowledge this map is true and accurate in its depiction of the mine.</p> <p>Mine Engineer _____ Date _____</p>	

