

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE		Page 1 of	
Permit Number	ACT/015/018 #10	Report Date	January 11, 1999
Mine Name	Deer Creek		
Company Name	Energy West Mining Company		
Excess Spoil Pile or Refuse Pile Identification	Pile Name	Waste Rock Disposal Site	
	Pile Number		
	MSHA ID Number	1211-UT-09-00121-02	
Inspection Date	December 29, 1998		
Inspected By	John Christensen/Rick Cullum		
Reason for Inspection <small>(Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)</small>	1998 Fourth Quarter Inspection		
	Attachments to Report? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes		
Field Evaluation			
<p>1. Foundation preparation, including the removal of all organic material and topsoil.</p> <p>All construction was done according to the permitted, professional engineered design specifications.</p>			
<p>2. Placement of underdrains and protective filter systems.</p> <p>An underdrain was installed when the site was constructed in 1989. the drain had a small amount of flow coming through it at the time of the inspection.</p>			
<p>3. Installation of final surface drainage systems.</p> <p>All interim slopes are maintained at their proper grade. The final slopes are surveyed to assure they are correct. Also the two final designed rip-rap ditches were installed as per the permitted plan and are extended as more lifts are added.</p>			

File in:

Confidential


Shelf

Expandable

Refer to Record No. 0058 Date 01/29/1999

In 0150018, 1999 Incoming

For additional information



4. Placement and compaction of fill materials.

The site was leveled in November 1998, trash and extraneous material were removed. Lift was sampled as required. The active lift is at approximately 20% capacity.


5. Final grading and revegetation of fill.

See No. 3.

The sub-soil berm surrounding the site was seeded shortly after construction.

6. Appearances of instability, structural weakness, and other hazardous conditions.

No weakness or instabilities are evident at this time.



7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

The total storage capacity of the Area No. 1 cell is 460,000 cubic yards. The elevation of the current lift varies with the required drainage slope. The surveyed elevation at the center of the active lift is 6,350 ft. The final design elevation will be 6,369 ft. The Area No. 1 cell is approximately 33% capacity.

The estimated volume of material hauled in 1998 to the site was 12,373 cubic yards, as of December 9, 1998.

Containment basins were constructed within the No. 1 cell to hold sediment from the cleaning of the Deer Creek mine site sediment pond. The cleaning was completed in December 1997.


The survey elevation of the active lift is 2ft. lower than last quarter. This is due to the sediment pond cleanings being excavated and redistributed over the entire site.


Certification Statement



I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: JOHN CHRISTENSEN, CONST. ENGINEER
(Full Name and Title)
Signature: John Christensen Date: 1/12/99
P.E. Number & State: 165651, UTAH





COPY

April 29, 1999

Utah Coal Regulatory Program
 Division of Oil, Gas and Mining
 1594 West North Temple, Suite 121 0
 Box 145801
 Salt Lake City, Utah 84114-5801

ACT/015/009 #10
 ACT/015/019 #4
 ACT/015/018 #4
 ACT/015/017 #10

Attention: Ms. Pamela Grubaugh-Littig

**Re: Submittal of Annual Report for 1998, PacifiCorp, Trail Mountain Mine,
 ACT/015/009, Cottonwood Mine, ACT/015/019, Deer Creek Mine,
 ACT/015/018, Des-Bee-Dove, ACT/015/017, Emery County, Utah.**

PacifiCorp, by and through its wholly-owned subsidiary, Energy West Mining Company as mine operator, herewith submit the Annual Report for 1998.

Please find enclosed two copies each of all forms and activities of the above mines related to coal mining and reclamation monitoring during the 1998 year, including the Subsidence and Hydrologic reports.


If there are any questions or concerns please call Dennis Oakley at 687-4825.

Sincerely,

Charles A. Semborski
 Geology/Environmental Supervisor

cc: Blake Webster
 Carl Pollastro
 Barbara Adams (File)

I:\PCCOMMON\COMMON\ENVIRONM\PERMITS\ANNUAL98.COR



Huntington Office:
 (435) 687-9821
 Fax (435) 687-2695
 Purchasing Fax (435) 687-9092

Deer Creek Mine:
 (435) 687-2317
 Fax (435) 687-2285

Trail Mountain Mine:
 (435) 748-2140
 Fax (435) 748-5125

Permit Number ACT/015/018 #10 **Report Date** January 11, 1999

Mine Name Deer Creek

Company Name Energy West Mining Company

Excess Spoil Pile or Refuse Pile Identification **Pile Name** ELK CANYON/ORIGINAL SITE

Pile Number

MSHA ID Number 1211-UT-09-0041

Inspection Date December 29, 1998

Inspected By John Christensen/Rick Cullum

Reason for Inspection 1998 Fourth Quarter Inspection
(Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)

Attachments to Report? No Yes

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.


The construction of both sites have been complete for some time in excess of 8 years. The foundations appear to be stable.

2. Placement of underdrains and protective filter systems.

None

3. Installation of final surface drainage systems.

The slopes of both sites have no rills, gullies or sloughage present. A rill to the east of the retaining wall will be monitored for change. There was no change in this rill from the last inspection.



4. Placement and compaction of fill materials.

No fill material is being placed at either site, since both are at their designed capacity. The Elk Canyon site contains approximately 24,000 cubic yards and the original site 90,000 cubic yards of fill material.

5. Final grading and revegetation of fill.

The sites are at capacity. The final grades are established and are revegetated.

6. Appearances of instability, structural weakness, and other hazardous conditions.

None were observed.

7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

On 12/29/98 there was no coal stored in the Elk Canyon pad. The seep at the base of the refuse pile was slightly damp.

**Certification
Statement**



I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: John Christensen, Construction Engineer
(Full Name and Title)

Signature: *John Christensen* Date: 11/12/99

P.E. Number & State: 165651 UTAH



ACT/015/018 #6

Permit Number	ACT/015/018	Report Date	JUNE 21, 1999
Mine Name	Deer Creek		
Company Name	Energy West Mining Company		
Excess Spoil Pile or Refuse Pile Identification	Pile Name	ELK CANYON/ORIGINAL SITE	
	Pile Number		
	MSHA ID Number	1211-UT-09-0041	
Inspection Date	JUNE 16, 1999		
Inspected By	John Christensen/Rick Cullum		

Reason for Inspection <small>(Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)</small>	1999 2ND Quarter Inspection
	Attachments to Report? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

The construction of both sites have been complete for some time in excess of 8 years. The foundations appear to be stable.

2. Placement of underdrains and protective filter systems.

None

3. Installation of final surface drainage systems.

The slopes of both sites have no rills, gullies or sloughage present. A rill to the east of the retaining wall will be monitored for change. There was no change in this rill from the last inspection.

4. Placement and compaction of fill materials.

No fill material is being placed at either site, since both are at their designed capacity. The Elk Canyon site contains approximately 24,000 cubic yards and the original site 90,000 cubic yards of fill material.

5. Final grading and revegetation of fill.

The sites are at capacity. The final grades are established and are revegetated.


6. Appearances of instability, structural weakness, and other hazardous conditions.

None were observed.

7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

On 6/16/99 there was approximately 200 tons of coal stored in the Elk Canyon pad. The seep at the base of the original refuse pile was slightly damp.

**Certification
Statement**



I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: JOHN CHRISTENSEN, SR. CONST. ENG.
(Full Name and Title)

Signature: *John Christensen* Date: 8/27/99

P.E. Number & State: 165651, UTAH



ACT/015/018 #60

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE		Page 1 of	
Permit Number	ACT/015/018	Report Date	Sept. 28, 1999
Mine Name	Deer Creek		
Company Name	Energy West Mining Company		
Excess Spoil Pile or Refuse Pile Identification	Pile Name	ELK CANYON/ORIGINAL SITE	
	Pile Number		
	MSHA ID Number	1211-UT-09-00121-01	
Inspection Date	Sept. 25, 1999		
Inspected By	John Christensen/Rick Cullum		
Reason for Inspection <small>(Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)</small>		1999 Third Quarter Inspection	
		Attachments to Report? <input type="checkbox"/> No <input type="checkbox"/> Yes	
Field Evaluation			
<p>1. Foundation preparation, including the removal of all organic material and topsoil.</p> <p>The construction of both sites have been complete for some time in excess of 8 years. The foundations appear to be stable.</p>			
<p>2. Placement of underdrains and protective filter systems.</p> <p>None</p>			
<p>3. Installation of final surface drainage systems.</p> <p>The slopes of both sites have no rills, gullies or sloughage present.</p>			

4. Placement and compaction of fill materials.

No fill material is being placed at either site, since both are at their designed capacity. The Elk Canyon site contains approximately 24,000 cubic yards and the original site 90,000 cubic yards of fill material.

5. Final grading and revegetation of fill.

The sites are at capacity. The final grades are established and are revegetated.


6. Appearances of instability, structural weakness, and other hazardous conditions.

None were observed.

7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

There was no coal stored in the Elk Canyon pad at the time of inspection. The seep at the base of the refuse pile was slightly damp.

**Certification
Statement**



I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: JOHN CHRISTENSEN SR. CONST. ENG.
(Full Name and Title)

Signature: John Christensen Date: 9/28/99

P.E. Number & State: 165651 UTAH

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE		Page 1 of	
Permit Number	ACT/015/018	Report Date	Sept. 28, 1999
Mine Name	Deer Creek		
Company Name	Energy West Mining Company		
Excess Spoil Pile or Refuse Pile Identification	Pile Name	Waste Rock Disposal Site	
	Pile Number		
	MSHA ID Number	1211-UT-09-00121-02	
Inspection Date	Sept. 24, 1999		
Inspected By	John Christensen/Rick Cullum		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		1999 Third Quarter Inspection	
		Attachments to Report? <input type="checkbox"/> No <input type="checkbox"/> Yes	
Field Evaluation			
<p>1. Foundation preparation, including the removal of all organic material and topsoil.</p> <p>All construction was done according to the permitted, professional engineered design specifications.</p>			
<p>2. Placement of underdrains and protective filter systems.</p> <p>An underdrain was installed when the site was constructed in 1989. the drain had a small amount of flow coming through it at the time of the inspection.</p>			
<p>3. Installation of final surface drainage systems.</p> <p>All interim slopes are maintained at their proper grade. The final slopes are surveyed to assure they are correct. Also the two final designed rip-rap ditches were installed as per the permitted plan and are extended as more lifts are added.</p>			

4. Placement and compaction of fill materials.

The site was leveled in the 3rd quarter of 1999, trash and extraneous material were removed. Lift was sampled as required. The active lift is at approximately 5% capacity.

5. Final grading and revegetation of fill.

See No. 3.

The sub-soil berm surrounding the site was seeded shortly after construction.

6. Appearances of instability, structural weakness, and other hazardous conditions.


No weakness or instabilities are evident at this time.

7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

The total storage capacity of the Area No. 1 cell is 460,000 cubic yards. The elevation of the current lift varies with the required drainage slope. The surveyed elevation at the center of the active lift is 6,349 ft. The final design elevation will be 6,369 ft. The Area No. 1 cell is approximately 36% capacity.

The estimated volume of material hauled in 1999 to the site was 4,230 cubic yards, as of September 1, 1999.

Certification Statement



I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: JOHN CHRISTENSEN, SR. CONST. ENG.
(Full Name and Title)

Signature: John Christensen Date: 9/28/99

P.E. Number & State: 165651, UTAH

ACT/015/018 #6

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE		Page 1 of	
Permit Number	ACT/015/018	Report Date	Dec. 16, 1999
Mine Name	Deer Creek		
Company Name	Energy West Mining Company		
Excess Spoil Pile or Refuse Pile Identification	Pile Name	Waste Rock Disposal Site	
	Pile Number		
	MSHA ID Number	1211-UT-09-00121-02	
Inspection Date	Dec. 15, 1999		
Inspected By	John Christensen/Rick Cullum		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		1999 Fourth Quarter Inspection	
		Attachments to Report? <input type="checkbox"/> No <input type="checkbox"/> Yes	
Field Evaluation			
<p>1. Foundation preparation, including the removal of all organic material and topsoil.</p> <p>All construction was done according to the permitted, professional engineered design specifications.</p>			
<p>2. Placement of underdrains and protective filter systems.</p> <p>An underdrain was installed when the site was constructed in 1989. The drain had a small amount of flow coming through it at the time of the inspection.</p>			
<p>3. Installation of final surface drainage systems.</p> <p>All interim slopes are maintained at their proper grade. The final slopes are surveyed to assure they are correct. Also the two final designed rip-rap ditches were installed as per the permitted plan and are extended as more lifts are added.</p>			

RECEIVED

DEC 20 1999

DIVISION OF OIL, GAS & MINING

4. Placement and compaction of fill materials.

The site was leveled in the 3rd quarter of 1999, trash and extraneous material were removed. Lift was sampled as required. The active lift is at approximately 5% capacity.

5. Final grading and revegetation of fill.

See No. 3.

The sub-soil berm surrounding the site was seeded shortly after construction.

6. Appearances of instability, structural weakness, and other hazardous conditions.

No weakness or instabilities are evident at this time.


7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

The total storage capacity of the Area No. 1 cell is 460,000 cubic yards. The elevation of the current lift varies with the required drainage slope. The surveyed elevation at the center of the active lift is 6,349 ft. The final design elevation will be 6,369 ft. The Area No. 1 cell is approximately 36% capacity.

The estimated volume of material hauled in 1999 to the site was 4,457 cubic yards, as of November 1, 1999.

Refuse being hauled to the site has been minimal due to good geologic conditions at the Deer Creek Mine.

Certification Statement



I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: JOHN CHRISTENSEN, SR. CONSTRUCTION ENGINEER
(Full Name and Title)

Signature: John Christensen Date: 12/16/99

P.E. Number & State: 165651 UTAH



RECEIVED

DEC 20 1999

DIVISION OF OIL, GAS & MINING


December 16, 1999

Ms. Pamela Grubaugh-Littig
Permit Supervisor
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801

Dear Ms. Grubaugh-Littig:

I am enclosing for submittal the 4th quarter 1999 Engineering Inspection Reports for Cottonwood/Wilberg and Des Bee Dove Waste Rock Site and old Waste Rock Site. Also, the Deer Creek Waste Rock Site and Elk Canyon/Original Site are enclosed.

Sincerely,



John Christensen, P.E.
Sr. Construction Engineer

Encls.

cc J. Blake Webster

Huntington Office:
(801) 687-9821
Fax (801) 687-2695
Purchasing Fax (801) 687-9092

Deer Creek Mine:
(801) 381-2317
Fax (801) 381-2285

Cottonwood Mine:
(801) 748-2319
Fax (801) 748-2380

ACT/015/018#6

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE		Page 1 of
Permit Number	ACT/015/018	Report Date Dec. 16, 1999
Mine Name	Deer Creek	
Company Name	Energy West Mining Company	
Excess Spoil Pile or Refuse Pile Identification	Pile Name	ELK CANYON/ORIGINAL SITE
	Pile Number	
	MSHA ID Number	1211-UT-09-00121-01
Inspection Date	Dec 15, 1999	
Inspected By	John Christensen/Rick Cullum	
Reason for Inspection <small>(Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)</small>	1999 Fourth Quarter Inspection	
	Attachments to Report? <input type="checkbox"/> No <input type="checkbox"/> Yes	
Field Evaluation		
<p>1. Foundation preparation, including the removal of all organic material and topsoil.</p> <p>The construction of both sites have been complete for some time in excess of 8 years. The foundations appear to be stable.</p>		
<p>2. Placement of underdrains and protective filter systems.</p> <p>None</p>		
<p>3. Installation of final surface drainage systems.</p> <p>The slopes of both sites have no rills, gullies or sloughage present.</p>		

RECEIVED

DEC 20 1999

DIVISION OF OIL, GAS & MINING

4. Placement and compaction of fill materials.

No fill material is being placed at either site, since both are at their designed capacity. The Elk Canyon site contains approximately 24,000 cubic yards and the original site 90,000 cubic yards of fill material. This site was covered with recent snow fall.

5. Final grading and revegetation of fill.

The sites are at capacity. The final grades are established and are revegetated.

6. Appearances of instability, structural weakness, and other hazardous conditions.

None were observed.

7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

There was no coal stored in the Elk Canyon pad at the time of inspection.

Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

[Cert. Stamp]

By: JOHN CHRISTENSEN SR. CONSTRUCTION ENGINEER
(Full Name and Title)

Signature: *John Christensen* Date: 12/16/99

P.E. Number & State: 165651 UTAH





RECEIVED

DEC 20 1999

DIVISION OF OIL, GAS & MINING

December 16, 1999

Ms. Pamela Grubaugh-Littig
Permit Supervisor
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801

Dear Ms. Grubaugh-Littig:

I am enclosing for submittal the 4th quarter 1999 Engineering Inspection Reports for Cottonwood/Wilberg and Des Bee Dove Waste Rock Site and old Waste Rock Site. Also, the Deer Creek Waste Rock Site and Elk Canyon/Original Site are enclosed.

Sincerely,

John Christensen, P.E.
Sr. Construction Engineer

Encls.

cc J. Blake Webster

Huntington Office:
(801) 687-9821
Fax (801) 687-2695
Purchasing Fax (801) 687-9092

Deer Creek Mine:
(801) 381-2317
Fax (801) 381-2285

Cottonwood Mine:
(801) 748-2319
Fax (801) 748-2380