



**State of Utah**  
 DEPARTMENT OF NATURAL RESOURCES  
 MICHAEL R. STYLER  
*Executive Director*  
 Division of Oil, Gas and Mining  
 JOHN R. BAZA  
*Division Director*

# Inspection Report

Permit Number:	<b>C0150025</b>
Inspection Type:	IND PART OVERSITE
Inspection Date:	Thursday, March 03, 2016
Start Date/Time:	3/3/2016 8:00:00 AM
End Date/Time:	3/3/2016 12:00:00 PM
Last Inspection:	Wednesday, February 10, 2016

Representatives Present During the Inspection:	
OSM	Spencer Shumate
OGM	Karl Houskeeper
Company	Kenny Defa

Inspector: Karl Houskeeper  
 Weather: Clear Skies, Temp. 63 Deg. F.  
 InspectionID Report Number: 5454  
 Accepted by: JHELFRIC  
 3/8/2016

Permittee: **CASTLE VALLEY MINING LLC**  
 Operator: **CASTLE VALLEY MINING LLC**  
 Site: **BEAR CANYON MINE**  
 Address: **2352 NORTH 7TH STREET, UNIT B, GRAND JUNCTION CO 81501**  
 County: **EMERY**  
 Permit Type: **PERMANENT COAL PROGRAM**  
 Permit Status: **ACTIVE**

Current Acreages		Mineral Ownership	Types of Operations
10,991.83	<b>Total Permitted</b>	<input checked="" type="checkbox"/> Federal	<input checked="" type="checkbox"/> Underground
35.02	<b>Total Disturbed</b>	<input type="checkbox"/> State	<input type="checkbox"/> Surface
	<b>Phase I</b>	<input type="checkbox"/> County	<input type="checkbox"/> Loadout
	<b>Phase II</b>	<input checked="" type="checkbox"/> Fee	<input type="checkbox"/> Processing
	<b>Phase III</b>	<input type="checkbox"/> Other	<input type="checkbox"/> Reprocessing

**Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:**

The inspection is an independent partial over site conducted by the (OSM) Office of Surface Mining and Reclamation, Spencer Shumate, as a follow up inspection from the OSM inspection conducted on 05/13/2015.

Five compliance issues were identified as concerns by OSM during the inspection. The five items are listed below and will be addressed by one (TDN) Ten Day Notice from OSM to the State of Utah:

- #1 Non Coal Waste (see item 8)
- #2 Stream Buffer (see item 22)
- #3 Other Sediment Control (see item 4c)
- #4 Support Facilities (see item 18)
- #5 Diversions (see item 4a)

This same items were concerns for OSM during their 05/13/2015 inspection visit. State Violations were issued at that time of which several were vacated thereafter.

*Karl R. Houskeeper*

**Inspector's Signature:**

**Date** Thursday, March 03, 2016

Karl Houskeeper,  
 Inspector ID Number: 49



**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining. telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

## **2. Signs and Markers**

The mine identification sign was observed at the entrance into the mining permit area and contained all of the required information.

### **4.a Hydrologic Balance: Diversions**

C-4D outlet, located by the fuel storage area and road access into the shop area was between 50 % to 75 % full of sediment during the inspection.

Numerous culvert inlets along side of the portal access road contained snow and mud mixtures.

Inlet of C-6D Was approximately 75% full of sediment. This inlet is on the pad area of the shop and directly behind a grease trap used to catch fluids and sediment from vehicles that are cleaned. The grease trap was completely filled and needs to be cleaned out.

The diversion that runs behind the shop area had numerous items of non coal waste, pallets, wood and wires.

### **4.b Hydrologic Balance: Sediment Ponds and Impoundments**

Trash was observed in all of the sediment ponds and sediment from a pond cleaning is on the bank of sediment pond A. The Trash in the sediment ponds along with the pond cleaning sediment of the bank were of concern to OSM (see item 8).

### **4.c Hydrologic Balance: Other Sediment Control Measures**

The ASCA Alternative Sediment Control Areas Along the access road to the main portal area were observed. OSM Commented that a few of these areas associated with the switch backs along the access road showed signs that work had been completed since the previous OSM inspection.

Numerous other ASCA areas were observed and contained snow/ice and mud from road usage and maintenance. These ASCA sites were of concern to OSM. Most of these areas were associated with culvert inlets.

## **8. Noncoal Waste**

Noncoal waste items were observed in all of the sediment ponds, parking area, diversions and pad areas. Noncoal waste was throughout the mine site.

**18. Support Facilities, Utility Installations**

OSM expressed concerns that conveyor covers and pan lines are not maintained or installed properly to prevent coal accumulation on the ground with-in the conveyor corridor. Coal was observed in these areas of concern during the inspection.

Water was observed coming out of the load out belt conveyor portal. Probably from wash down. This water was coming out and then depositing coal on to the asphalt roadway of the load out area. The water was draining across the road way and then into the road diversion.

Material was being stored in wooden boxes above and to the side of the main portal access area. Questions were raised as whether this was an approved storage area. During the prior OSM inspection this area was requested to be cleaned and since that inspection material storage is taking place.

**22. Other**

OSM observed several areas where there are coal fines with-in the reaches of the designated stream buffer zones. Some areas had wood and old car parts. The company representative Kenny Defa indicated that residents had lived or occupied some of these same areas pre-law.

Coal is present on the ground under conveyor belt ways. OSM expressed concerns that conveyor covers and pan lines are not maintained or installed properly to prevent this coal accumulation on the ground.