



0022

STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

501  
Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

**INSPECTION REPORT**

INSPECTION DATE & TIME: Sept. 26, 1989  
10:00 a.m. to 2:00 p.m.

Permittee and/or Operators Name: Valley Camp of Utah  
Business Address: Scofield Route, Helper, Utah 84526  
Mine Name: Belina Complex Permit Number: ACT/007/001  
Type of Mining Activity: Underground  Surface  Other   
County: Carbon State: Utah  
Company Official(s): Steve Tanner  
State Official(s): Daron Haddock  
Partial:  XX Complete:  Date of Last Inspection: August 21, 1989  
Weather Conditions: Partly Cloudy, Cool  
Acreage: Permitted 3136 Disturbed 79 Regraded  Seeded  Bonded 79  
Enforcement Action: None

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( X )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( X )	( )	( )	( X )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( X )	( )	( )	( X )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION Sept. 26, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS:

Signs and markers around the mine are in place. A new sign marking the substitute topsoil at the Valcam loadout has been installed. This pile is being stored for future use in reclamation of the site.

4b. DIVERSIONS:

Diversions for the most part seem to be in good condition. A couple of places could use maintenance. The berm at the lower end of the road at sediment pond #4 should be beefed up.

4f. EFFLUENT LIMITATIONS:

Mine discharge pond #5 was discharging. Water appeared clear and no problems are expected with the water meeting effluent limitations.

12. BACKFILLING AND GRADING:

Portals for the Utah #2 mine are located on the East side of the railroad tracks at the Valcam loadout. MSHA has required the operator to backfill the portals as the Utah #2 mine is no longer operable. The portals are currently being backfilled. Soil material will then be placed over the portal site and then seeded.

Copy of this Report:

Mailed to: Steve Tanner (Valley Camp)

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Inspectors Signature and Number: Daron R. Haddock #28 Date: Sept. 28, 1989