



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Nov. 28, 1989
1:30 p.m. to 3:30 p.m.

Permittee and/or Operators Name: VALLEY CAMP OF UTAH
Business Address: SCOFIELD ROUTE HELPER, UTAH 84526
Mine Name: BELINA COMPLEX Permit Number: ACT/007/001
Type of Mining Activity: Underground Surface Other
County: CARBON State: UTAH
Company Official(s): KIT PAPPAS
State Official(s): DARON HADDOCK
Partial: Complete: Date of Last Inspection: SEPT. 26, 1989
Weather Conditions: SUNNY, COOL
Acreage: Permitted 3136 Disturbed 79 Regraded Seeded Bonded 79
Enforcement Action: NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	(X)	()	()	(X)
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION Nov. 28, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS & MARKERS:

Disturbed area perimeter markers appear to have been recently painted. Other signs and markers are in good order as well.

4b. DIVERSIONS:

The mine site was recently covered by approximately 2 feet of new snow, which made it difficult to determine the condition of ditches and culverts.

All surface drainage appeared to be reporting to a sediment pond. No problems were visible.

A new drop drain has been installed near the truck dump at the Val Cam loadout.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

The sediment ponds were checked and found to have plenty of storage volume available for both sediment and water.

Mine discharge Pond 005 was discharging during the inspection. The water looked clear therefore, no sample was taken.

16d. ROAD MAINTENANCE:

A maintenance crew was working on snow removal. Snow is being stockpiled on a storage area north of the office in hopes of keeping road salt out of sediment Pond #4. Care is being taken to insure that all removed snow will eventually drain to a sediment pond.

Copy of this Report:

Mailed to: Kit Pappas, Valley Camp of Utah

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Inspectors Signature and Number: Daron R. Haddock #28 Date: Nov. 28, 1989