



INSPECTION REPORT  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001 DATE OF INSPECTION: April 7, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Diversions -

All diversions still could not be seen since 12" to 18" of snow is covering the ground. The NOV #93-39-1-1 was terminated since the abatement was accomplished. The elephant trunk should be installed on the downward culverts at the haul road from the mine site. This would eliminate the potential of the diversion eroding.

4b. Sediment Ponds -

All ponds were still covered with snow; therefore, the inlet and outlet could not be seen for erosion. No ponds were discharging during the time of inspection.

19. AVS Check -

An AVS check has been taken at the mine site with no new changes in ownership and control.

21. Insurance -

Enclosed is a renewal of the insurance accord form. The accord form complies with the requirements of the R645 regulations.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Valley Camp of Utah, Steve Tanner  
Mailed to: Bernie Freeman (OSM)  
Given to: Joe Helfrich (DOGM)  
Filed to: Price Field Office  
Date: April 15, 1993

Inspector's Signature and Number:

  
Stephen J. Demczak

#39