

AGH
JAH



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Partial: XX Complete: Exploration

Inspection Date/Time: September 24, 1993/09:00am-10:00am
Date of Last Inspection: September 9, 1993

Mine Name: Belina Complex County: Carbon Permit Number: ACT/007/001
Permittee and/or Operator's Name: Valley Camp of Utah
Business Address: Scofield Route, Helper, UT 84526
Type of Mining Activity: Underground XX Surface Prep. Plant Other
Officials(s): State: Stephen J. Demczak Company:
Federal Official(s): Weather Conditions: Warm 70's
Existing Acreage: Permitted-3136 Disturbed-79 Regraded- Seeded- Bonded-79
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ X Active/ Inactive/ Temp Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[]	[XX]	[XX]
2. SIGNS AND MARKERS	[XX]	[]	[XX]	[]
3. TOPSOIL	[]	[]	[]	[]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[]	[]	[]	[]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[]	[XX]	[]
c. OTHER SEDIMENT CONTROL MEASURES	[]	[]	[]	[]
d. WATER MONITORING	[]	[]	[]	[]
e. EFFLUENT LIMITATIONS	[]	[]	[]	[]
5. EXPLOSIVES	[]	[]	[]	[]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[]	[]	[]	[]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[]	[]	[]	[]
8. NONCOAL WASTE	[]	[]	[]	[]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[]	[]	[]	[]
10. SLIDES AND OTHER DAMAGE	[]	[]	[]	[]
11. CONTEMPORANEOUS RECLAMATION	[]	[]	[]	[]
12. BACKFILLING AND GRADING	[]	[]	[]	[]
13. REVEGETATION	[]	[]	[]	[]
14. SUBSIDENCE CONTROL	[]	[]	[]	[]
15. CESSATION OF OPERATIONS	[]	[]	[]	[]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[]	[]	[]	[]
b. DRAINAGE CONTROLS	[]	[]	[]	[]
17. OTHER TRANSPORTATION FACILITIES	[]	[]	[]	[]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[]	[]	[]	[]
19. AVS CHECK (4th Quarter-April, May, June) <u> </u> date	[XX]	[]	[XX]	[]
20. AIR QUALITY PERMIT	[]	[]	[]	[]
21. BONDING & INSURANCE	[]	[]	[]	[]

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001 DATE OF INSPECTION: September 24, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

The identification signs at all access gates of Valley Camp were replaced with White Oak Mining and Construction. The site had White Oak employees on the surface and underground. Coal had been mined due to the fact coal was stacked around the coal silo at the mine site. The inspection prior, all coal at the mine site was removed and taken to the loadout facility. On the morning of September 27, 1993 no information was received by the Division for a permit transfer by Valley Camp of Utah, Inc. Therefore, a NOV 93-39-6-1 was written for failure to obtain prior written approval in accordance with R645-303-300 before transferring, assigning or the sale of rights granted by a permit.

2. Signs and Markers -

The identification signs of Valley Camp of Utah was removed and White Oak Mining and Construction was placed.

4a. Diversions -

The mine pond 004A was inspected and determined that the pond was below the 60% sediment volume level. Therefore, 93-39-4-1 was terminated.

19. AVS Check -

An AVS check was made and no change in ownership or control was made as of September 24, 1993. The identification signs were removed and had the ACT/007/001 identification number put on White oak Mining and Construction signs.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Valley Camp of Utah, Steve Tanner

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: October 5, 1993

Inspector's Signature and Number: Stephen J. Demczak

Stephen J. Demczak

#39