

July 8, 1982

Inspection Memo
to Coal FileRE: Price River Coal Company
Price River Coal Complex
ACT/007/004
Carbon County, Utah

A partial inspection was conducted at Price River Coal's Crandall Canyon development site on May 20, 1982 by Division Inspector David Lof. He was accompanied on the inspection by Rob Wiley of Price River Coal.

The sediment pond had been cleaned as requested during the April 13, 1982 partial inspection. The materials which had been removed from the sediment pond were placed just above the site proposed for sediment pond 013. This site is able to afford some runoff controls due to the pond having already been partially excavated. However, the operator was asked to better consolidate the materials and implement better runoff controls by May 24, 1982 in order to positively ensure adequate runoff control.

The disturbed area runoff diversion which carries muck water from the #1 shaft to the sediment pond was in need of maintenance. The operator was given until May 24, 1982 in order to have the diversion properly maintained.

The undisturbed runoff diversion ditch on the west side of the road to the substation, and the undisturbed runoff diversion channel above the #2 shaft needed to be better defined. The operator was given one month in order to accomplish this.

The topsoil stockpile near the junction of the mine access road by Highway 6 needed to be recontoured on the west side because it had been disturbed by construction activity on the new mine access road. The operator was given one month to have the recontouring completed.


DAVID LOF
RECLAMATION OFFICER

DL/tck

cc: Tom Ehmett, OSM
Rob Wiley, Price River Coal Company
Inspection Staff

Statistics:

See Skyline Mine memo dated July 7, 1982