

Document Information Form

Mine Number: C/007/004

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A.

Date Sent: JUNE 29, 1982

Explanation:

INSPECTION MEMO TO COAL FILE.

cc:

File in: C/007, 004, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

June 29, 1982

Inspection to
Coal File

RE: Price River Coal Company
Price River Coal Complex
ACT/007/004
Carbon County, Utah

On May 6, 1982, Division inspectors David Lof and Joe Helfrich visited the Castlegate preparation plant site. They were accompanied on the visit by Mr. Ken Hutchinson of Price River Coal Company. The purpose of the visit was to conduct a follow-up inspection on several remedial action required during the April 13, 1982 inspection.

The operator had been given one week in order to comply with the following:

- a. Remove the snow removal waste material from the south embankment of the clear water overflow pond.
- b. Repair the berm around the overflow pond.
- c. Grade the road on the south side of the pond, so that runoff would flow to the south side of the road.
- d. Install a small catch basin across the road from the southwest corner of the sediment pond.
- e. Repair the berm and inlet at the northeast corner of the thickener overflow pond.

At the time of this inspection, the work had been completed.

The operator had removed better than half of the coal processing waste which had been placed on the new stack tube pad during the winter due to poor road conditions to the coarse refuse dump. The operator had been given 30 days in order to comply with the remedial actions required therefore, at the time of this inspection he had one week in order to complete the removal of the coal processing waste.

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0028 Date 6-29-82

In C/ 007, 004, Internal

For additional information

INSPECTION MEMO
ACT/007/004
June 29, 1982
Page 2

During the March complete inspection the operator had been given 30 days in order to clean the sediment basin at Utah Fuel #1. Because of equipment breakdown the operator was given until May 13, to have the sediment basin cleaned. At the time of this inspection, a large berm had been placed around the sediment basin. A straw bale dike was in place along the perimeter of the Utah Fuel #1 disturbed area and some sediment had been removed from the sediment basin.



DAVID LOF
RECLAMATION OFFICER

DL/tck

cc: Tom Ehmett, OSM
Rob Wiley, Price River Coal Company
Inspection Staff

Statistics:

See Wilberg Mine memo dated June 29, 1982