

December 5, 1983

Inspection Memo
to Coal File:

RE: Price River Coal Complex
Price River Coal Company
ACT/007/004, Folder #7
Carbon County, Utah

A follow up inspection was conducted by Sandy Pruitt on September 8, 1983. Frank Pero, Price River Coal Company, accompanied this inspector on a brief tour of Crandall Canyon and Sowbelly Canyon Mine sites. The purpose of this inspection was to insure that surface grading done along the road and pad area below shaft #1 was done promptly upon completion of the Hilfaker Wall construction, and was adequate to convey all disturbed area drainage towards the sediment pond by shaft #2. This inspection determined that exactly that had been accomplished. In addition the lowest water bar in Sowbelly Canyon had been reestablished as requested during the last inspection so that there was no potential for disturbed area drainage overflowing down the road and offsite. No compliance problems were detected during this inspection.

SANDY FRUITT 
FIELD SPECIALIST

SP:re

cc: Tom Ermett, OSM
Joe Helfrich, DOGM
Rob Wiley, PRCC

Statistics: See Genwal Mine memo dated September 23, 1983