

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/005 DATE OF INSPECTION: July 13, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

3. Topsoil -

The expansion to open the coal storage yard at the track/coal train loadout facility has increased the topsoil storage at the site. The company was in the process of moving the material to the storage facility.

4b. Sediment Ponds and Impoundments -

The upper sediment pond at the mine site will be in the process of being closed out. The company tried earlier in the month to clean the pond but the new removal process did not work.

The lower pond at the loadout facility was being expanded to facilitate the increased size of the coal storage yard.

4c. Other Sediment Control Measures -

There were two locations that straw bales would need to be changed out due to wildlife eating the bales.

7. Coal Mine Waste/Refuse Piles/Impoundments -

It is predicted that all the refuse material for this year has been brought to the refuse pile. The material will be compacted shortly.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Coastal States Energy/Utah Fuel, Keith Zobel
Mailed to: Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM)
Filed to: Price Field Office
Date: July 14, 1993

Inspector's Signature and Number:


Stephen J. Demczak

#39