

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/005

DATE OF INSPECTION: January 19, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Diversions -

The diversions were clear and functioning as designed. A culvert was being unplugged from ice build-up caused from the extreme temperature changes and no snow to act as insulation for the culvert. Ice was found throughout the ditches but will turn into water later on in the day.

4b. Sediment Ponds and Impoundments -

The sediment pond at the mine site was discharging and there were no signs of hazardous conditions existing. The loadout ponds were partially filled with water and a possibility of discharge would occur if warm temperatures continue.

4c. Other Sediment Control Measures -

Silt fences and straw bales were inspected and maintenance will be required on a section of fences at the loadout. Operator will be adding new fences.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Coastal States Energy/Utah Fuel, Keith Zobell


Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: January 21, 1994

Inspector's Signature and Number:


Stephen J. Demczak

#39