

*COPY TO FOLDER #1
DAVE L.
WAYNE*

0066

FILE ORIGINAL

THANKS

U MINING COMPANY

Subsidiary of Getty Oil Company
MC Price, Utah 84501
Telephone (801) 637-2875

FILE ACT/007/006
FOLDER #7
RECEIVED

MAY 10 1984

**DIVISION OF OIL
GAS & MINING**

RECEIVED

Mining
ing
4114

**DIVISION OF OIL
GAS & MINING**

RE: NOV 84-4-7-6 - 4 of 6

Dear David:

There seems to be some confusion as to the status of the Class II Road Regulations. The Federal regulations were suspended and, I believe, have been rewritten. I also believe that the Division is revising the State regulations.

Regardless of the status of the regulations at this time, we will maintain the road in accordance with UMC 817.163. Surface dips have been constructed at approximately 200 foot intervals or less.

The drainage ditch on the cut side will be lined with rock of the size specified in the Review of As-Built Runoff and Sedimentation Control Plan submitted to the Division on January 13, 1984; the specified size is one foot rock. If we cannot find rock of this size, we will use smaller rock and cement it in place to prevent dislocation from the water's velocity. If there are sections of the ditch where used conveyor belting will work, we would also propose to use it.

Sediment Trap No. 5, located at the bottom on Ditch No. 6A, will be maintained to settle out suspended solids.

If you have any questions or need additional information, please let me know.

Respectfully,

PLATEAU MINING COMPANY

Ben Grimes
Ben Grimes
Environmental Coordinator

BG:sd