

0013



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 21, 1988
9:00 a.m. to 12:00 p.m.

Permittee and/or Operators Name: Cyprus-Plateau Mining Co.
Business Address: P. O. Drawer PMC Price, Utah 84501
Mine Name: Star Point Permit Number: ACT/007/006
Type of Mining Activity: Underground Surface Other
County: Carbon State: Utah
Company Official (s): Bob Lauman
State Official(s): Bill Malencik and John Whitehead
Partial: XX Complete: Date of Last Inspection: June 20, 1988
Weather Conditions: Clear and warm; dry mine site
Acreage: Permitted 5225 Disturbed 221.65 Regraded Seeded Bonded 221.65
Enforcement Action: None; maintenance item underscored in report

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	(X)
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/006

DATE OF INSPECTION July 21, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

This partial inspection concentrated on field portion looking at environmental control measures associated with controlling runoff and erosion. The mine, since the last inspection, had been hit with three high intensity thunderstorms.

MAINTENANCE ITEMS:

Above pond #2 is a steep slope; the area has been seeded. The easterly portion is vegetated; the westerly portion is not successful. Some small rills are developing. The westerly area is in need of retreatment and/or additional protection. Since fall seedings are the most successful, it is recommended the operator rough-up the site, provide protection as needed and seed the area this fall. It is recommended the site preparation and seeding be done in one operation, preferably the fall of 1988.

2. SIGNS AND MARKERS:

Required signs and makers were observed and no problem noted.

4a. STREAM CHANNEL DIVERSIONS:

Stream channel diversion near the old tiple was observed and no problem noted.

4b. DIVERSIONS:

Diversion #23 was observed. It had recently been concrete lined. Also, recent storm required maintenance of this ditch. The ditch was reworked

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/006

DATE OF INSPECTION July 21, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

4b. DIVERSIONS (cont'd):

to prevent runoff from running outside of and along the edge of the concrete lining. It appeared that the work had been completed.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

Sediment pond #9 was reviewed. The clay liner has been installed. The pond is in the final stage of completion.

Copy of this Report:

Mailed to: Bob Lauman, PMC

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: William J. Malencik #26 Date: July 27, 1988