



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

*John P. [Signature]*

INSPECTION DATE & TIME: February 25, 1992, 2:20 pm - 4:00 pm  
February 26, 1992, 7:45 am - 9:30 am

Permittee and/or Operators Name: Cyprus-Plateau Mining Corporation  
Business Address: P.O. Box Drawer PMC, Price, Utah 84501  
Mine Name: Star Point Permit Number: ACT/007/006  
Type of Mining Activity: Underground X Surface      Other       
County: Carbon Company Official(s): 2/25:Jack Rogers, 2/26:Ben Grimes  
State Official(s): Hugh Klein, Henry Sauer  
Partial: X Complete:      Date of Last Inspection: January 29-30, 1992  
Weather Conditions: Clear and unseasonably warm  
Acreage: Permitted 7200 Disturbed 221 Regraded      Seeded      Bonded 221  
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( X )	( )	( )	( X )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( X )	( )	( )	( X )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT

(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/006

DATE OF INSPECTION: 2/25-26/1992

(Comments are Numbered to Correspond with Topics Listed Above)

4d. Hydrologic Balance: Other Sediment Control Measures

The culvert immediately below the upper tipple was torn and crushed. The flow of snowmelt drainage was slightly impeded. The culvert must be replace immediately.

6. Disposal of Development Waste and Spoil

Directly south of the main office, snow and debris from the Loin Deck Yard snow removal was downcast over the outslope of the pad area. Mr. Grimes presented to me the Division approval letter for this activity (letter from Joe Helfrich to Ben Grimes, dated 12/29/83).

12. Backfilling and Grading

The excavation created as a result of the underground diesel tank removal was in the process of being backfilled with subsoil and lithic material from the refuse pile expansion area.

Copy of this Report:

Mailed to: Ben Grimes-CPM, Bernie Freedmann-OSM

Given to: Joe Helfrich-DOGM

Inspectors Signature: Henry Fauer

#32

Date: 3/4/1992