


24 CC Van
Joe
Daron
Sharon P
Dare D
Ken W
Mike S
Jims
Bill M.

HUNTINGTON CATTLE ASSOCIATION

Lee McElprang
P.O. Box 448
Huntington, UT 84528
August 19, 1998



Lowell P. Braxton
Division Director
Division of Oil, Gas and Mining
P.O. Box 145801
Salt Lake City, UT 84114-5801

Subject: Star Point Spring


Dear Mr. Braxton,

The Huntington Cattle Association and the Huntington-Cleveland Irrigation Company wish to express our concern with the disappearance of water flows at the Star Point Spring on Gentry Mountain. We feel that the Plateau Mining operation is responsible for this situation and we feel that they should be held responsible for replacement of the water.

We appreciate your attention to our concerns.

Sincerely,

Lee McElprang - President
Huntington Cattle Association



Kay Jensen - President
Huntington-Cleveland Irrigation Company

USDA - Forest Service GRAZING PERMIT - PART 3 (Reference FSM 2230)	Page 10 of 14
	Permittee Number
	Permit Number

Special Terms and Conditions

Responsibilities for Construction and Maintenance of Structural Improvements or for Range Rehabilitation. (List the specific responsibilities of the permittee; or incorporate into the permit the cooperative agreement, management plan or other document which sets forth these responsibilities in detail. Fully identify the particular document or documents.)

The allotment permittee or permittees are responsible for the maintenance of all structural range improvements on this allotment. For allotments managed by an Association or Herd Manager specific maintenance responsibilities may be assigned to individual permittees by the Association President or Herd Manager. The standard of maintenance will be such that the effective life of the improvement will be perpetuated throughout the period of time it is required for the proper protection and management of this allotment. (See the Manti-La Sal National Forest's Maintenance Standards for Range Improvements.)

Range improvements will be maintained yearly, before livestock enter a unit, to the standard they were constructed.

The following improvements are located along or within the boundaries of this allotment:

Allotment # 301 Castle Valley Ridge
Improve.

Number	Improvement Name	Type	Year Const.	Length or Size	Location
30103	Star Point	Trough	1936	10'	Sec. 12, T15S, R7E
30104	Little Park #1	Trough	1966	10'	NW Sec. 11, T15S, R7E
30105	Little Park #2	Trough	1978	10'	NE Sec. 10, T15S, R7E
30106	Bear Wallow	Trough	1978	10'	SE Sec. 3, T15S, R7E
30107	S. Fk. Corner Canyon	Trough	1941	10'	NW Sec. 1, T15S, R7E
30108	N. Fk. Corner Canyon	Trough	1935	20'	SE Sec. 35, T14S, R7E
30109	Head of First Water	Trough	1935	10'	NE Sec. 27, T14S, R7E
30110	L. Fk. Second Water	Trough	1939	10'	NE Sec. 22, T14S, R7E
30111	First Water Ridge	Trough	1939	10'	Sec. 26, T14S, R7E
30124	Christensen	Trough	1979	10'	
30125	Lone Pine	Trough	1979	10'	SE Sec. 23, T14S, R7E

Fences

30101	Nuckwoodward Worm	Fence	1938	.2 mi	Sec. 15 , 22 T14S, R7E
30102	Nuckwoodward Wire	Fence	1977	2.5 mi	Sec. 15 , 22, 23 T14S, R7E 27, 34. <i>Sec 10 T15S, R7E</i>
30118	Bob Wright Boundary	Fence	1977	5.8 mi	Sec. 1, 12, 13 T14S, R7F 24, 25, 36. <i>Sec. 6, T15S, R8</i>
- 30121	Second Water Allotment	Fence	1979	.3 mi	Sec. 22, T14S, R7E
	Lone Pine Ridge	Fence	1980	.6 mi	Sec. 24, T14S, R7E
	Sinks - L. Park Div.	Fence	1983	2 Sections	Sec. 34, 35, T14S, R7E
	Second Water Fence	2 Fences	1994	Gates	Sec. 14, 23, T14S, R7E
	Corner Canyon Fence (Gate)		1994	Gates	Sec. 36, T14S, R7E
	First Water Fence (Gate)		1994	Gates	Sec. 25, T14S, R7E
	Castle Valley Ridge - Gentry	Fence			Sec. 11, 12 T15S, R7E
	Allot Boundary				

Pump


Dev Spring



- Commitments
- Journal Entry
- Thoughts & Ideas
- Agendas
- Conversations

September 1998
Daily Record of Events

Tuesday
251st Day 114 Left
Week 36



-Sketch/Photo Log prepared by DOGM, Joe Helfrich, on September 9, 1998 showing where each of the 13 photos were taken at the Starpoint Spring site.

-Photos are available for observation at either the Salt Lake or Price DOGM Offices. Photos are not enclosed as part of this inspection report.