



0059

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Jan. 7, 1988
1:00 p.m. to 4:00 p.m.

Permittee and/or Operators Name: Kaiser Coal Corporation
Business Address: P.O. Box D Sunnyside, Utah 84539
Mine Name: Sunnyside Permit Number: ACT/007/007
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): Barry Grosely
State Official(s): Bill Malencik
Partial: X Complete: Date of Last Inspection: Dec. 10, 1987
Weather Conditions: Snowing and cold; site snow covered
Acreage: Permitted 14475 Disturbed 310 Regraded Seeded Bonded 287
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	(X)	()	()	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/007

DATE OF INSPECTION Jan. 7, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

SIGNS AND MARKERS:

Sign was installed on the gate post near the refuse pile as specified in the November inspection report. Also, additional stream buffer zone signs were placed along the Grassy Trail drainage.

4b. DIVERSIONS:

Although snow covered, the operator stated they had placed additional check dams/erosion protection concerning diversions mentioned in the November inspection report, items numbered 1, 2, and 3. Weather conditions precluded completing the work on diversion no. 2 and starting on diversion no. 4 (referenced in the November inspection report). Work will be completed as soon as weather conditions are conducive to installing riprap and installing 440 feet of culvert to replace a plastic liner.

Culverts mentioned in the November inspection report were not rechecked, but should be field checked on the next complete inspection, or when field conditions are propitious for such an inspection.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

The coarse refuse sediment pond, south of the railroad, was maintained by providing additional embankment erosion protection. A berm was constructed as suggested in the December inspection. While the embankment was covered with snow, the berm was visible.

4d. OTHER SEDIMENT CONTROL MEASURES:

The berm on the upper Iceland Wash check dam had been enlarged as specified in previous inspections. Also, the silt fence adjacent to the coarse refuse sediment pond had been replaced.

Copy of this Report:

Mailed to: Barry Grosely, KCC

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Inspectors Signature and Number: /s/ Wm. J. Malencik #26 Date: Jan. 12, 1988