

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/007

DATE OF INSPECTION: 7-10-95

(Comments are Numbered to Correspond with Topics Listed Above)

9. PROTECTION OF FISH, WILDLIFE, AND RELATED ENVIRONMENTAL VALUES

At the request of Mr. Ken Rushton, Trustee responsible for the Sunnyside bankruptcy/site at this time, a courtesy inspection was conducted this day to ascertain the condition of the Pole Canyon air shaft, i.e., has the shaft been sealed?

Based on my inspection, the following items were determined;

- 1) the air shaft **has been sealed** with an 11 foot by 11 foot concrete cap with a vent cap installed.
- 2) the silt fence, which had been installed to treat the pad runoff at the intersection of the access road and the pad, has been removed and has not been replaced.
- 3) the boulders, which blocked access to this ASCA, have been removed from the road and not replaced, allowing machinery and general public access to the site.

Based on a concern from a U. S. Department of Labor, Mine Safety and Health Administration inspector, the PCB contaminated transformers which have been placed in storage in the shop building were also inspected this day. One of the contaminated transformers has been tipped allowing PCB oil to spill and accumulate inside the berm. This has been reported to Mr. Henry Sauer, who is the regularly assigned DOGM inspector. It was Mr. Sauer's intent to notify JBR Consultant's about mitigating this spill.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Ken Ruston, SCC Trustee

Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: July 14, 1995

Inspector's Signature: _____



#46

Peter Hess