

INSPECTION REPORT
(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/007

DATE OF INSPECTION: 4/2/96

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS

All portions of the disturbed area at the mine were barren of snow during this inspection. In general, there is little if any change in conditions at the site.

2. SIGNS AND MARKERS

Many of the disturbed area perimeter markers have been removed by individuals for their personal use or damaged.

4a. HYDROLOGIC BALANCE: DIVERSIONS

Many of the drainage culverts at the site are becoming blocked with sediment.

4c. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Many of the silt fences at the site are by passing.

8. NONCOAL WASTE

The Manshaft area and the #2 Canyon area are noncoal waste environmental disasters.

9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES

The portals at the Outcrop area of the #1 Mine slope which were backfilled in September of 1995 were inspected.

There are no visible signs of vandals attempting to gain access to the mine workings through these areas. Settling of the placed material is nil.

INSPECTION REPORT
(Continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/007

DATE OF INSPECTION: 4/2/96

(Comments are Numbered to Correspond with Topics Listed Above)

16a. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

The access road to the Outcrop area mentioned above is in extremely poor condition. Drainages cross this road in several locations and runoff has washed large (approximately 12 inch) angular rocks across one of the crossings.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Ken Rushton (Trustee)


Marcia Petta (OSM)

Given to: Joe Helfrich (DOGMA)

Filed to: Price Field Office

Date: April 2, 1996

Inspector's Signature: _____



#46

Peter Hess