

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION: 10/28/94

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS -

Inspected the perimeter markers at the Wellington Prep. site. Several markers have been taken out by vandals and will be replaced by the operator. These missing signs were located near the main line railroad tracks.

4a. DIVERSIONS -

The diversions were spot checked with a couple of ditches needing maintenance due to sediment build-up. Presently this is not a violation because the diversions are oversized.

4c. OTHER SEDIMENT CONTROL -

Several alternate sediment control areas were inspected with maintenance being needed at one site. Water has started to undercut the straw bales but has not bypassed the bales for sediment control. Operator has committed to correct this problem.

11. CONTEMPORANEOUS RECLAMATION -

The division is in the process of drafting a DIVISION ORDER to the permittee to comply with the R645-301-352 regulation. The operator will need to update the Mining and Reclamation Permit with regards to Contemporaneous Reclamation of the Course Refuse Pile.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Jay Marshall (NEICO)

Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: November 2, 1994

Inspector's Signature: _____

Stephen J. Demczak

#39