



OGMCOAL DNR <ogmcoal@utah.gov>

Hiawatha Inspection Report 6205

Priscilla Burton <priscillaburton@utah.gov>

Tue, Aug 14, 2018 at 5:14 PM

To: Dana Jenkins <hannahsknight@yahoo.com>, "Charles Reynolds (Google Drive)" <charles.reynolds@hiawathacoal.com>, OGMCOAL DNR <ogmcoal@utah.gov>

Cc: Karl Houskeeper <karlhouskeeper@utah.gov>, Steve Christensen <stevechristensen@utah.gov>, Chris Rohrer <chrisrohrer@utah.gov>

Hello Dana and Charles,

I have attached a report of the Division's inspection of the Middle Fork and South Forks on July 31, 2018. During that inspection, the disturbed area boundary of the Middle Fork was discussed and noted. I checked the disturbed area boundary on Ex. V-5 and find a larger disturbed area boundary than that marked and discussed. The coal program related this information to Chris Rohrer and explained that scraping additional fill material from the approach to portals 29HO6/29HO7 would not be possible. In addition, this means that the contractor must stage within the disturbed boundary (because there is no room outside the boundary). Staging the equipment and work within the permit boundary will not result in a coal program violation as long as sediment controls are maintained. I do encourage you to make the disturbed area boundary markers visible to the contractor.

I hope the AMR project moves forward and is completed this fall.

Priscilla Burton
Division of Oil, Gas, & Mining
Price Field Office

cell: 435-609-1014
office: 435-613-3733
priscillaburton@utah.gov

 **7312018 Insp Rpt 6205.pdf**
717K