



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

*NR71*  
*[Signature]*

## INSPECTION REPORT

INSPECTION DATE & TIME: 2/27/90  
11:00 AM to 2:00 PM

Permittee and/or Operators Name: Genwall Coal Company  
Business Address: P.O. Box 766, Wellington, Utah 84542  
Mine Name: Wellington Prep Plant Permit Number: ACT/007/Q12  
Type of Mining Activity: Underground Surface Other Prep. Plant  
County: Carbon  
Company Official (s): Candy Manzanares  
State Official(s): Mike DeWeese  
Partial: XX Complete:          Date of Last Inspection: 1/25/90  
Weather Conditions: Clear skies, warm  
Acreage: Permitted 1720 Disturbed 356 Regraded 1.5 Seeded 1.5 Bonded 469  
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( X )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

**INSPECTION REPORT**  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION 2/27/90

(Comments are Numbered to Correspond with Topics Listed Above)

4b. DIVERSIONS

Evidence of recent maintenance on the existing diversion channels was present. The operator has rebuilt the embankments on several of the disturbed area diversions. No evidence of overtopping or excessive erosion was noted in any of the diversions.

4d. OTHER SEDIMENT CONTROL MEASURES

Topsoil stockpiles No.s 1-3 had functional berms around the perimeter at the time of inspection. Topsoil stockpile No.4 was under supplemental construction during the inspection. The containment berm around Stockpile No. 4 was being reconstructed and the slope between the county road and the stockpile was being regraded to eliminate rills. The operator was informed that upon completion of construction the regraded area would have to be reseeded with an approved seed mix.

4e. Surface and Ground Water Monitoring

The ground water monitoring wells were inspected and found to be appropriately sealed according to applicable criteria.

Copy of this Report:

Mailed to: Brian Smith-OSMRE, Candy Manzanares-GCC, Gus Manwarring-GCC  
Given to: Darren Haddock-DOGM

Inspectors Signature and Number: M. De Zure #31 Date: 3/5/90