



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertor
Governor

Dee C. Hansen
Executive Director

Dianna R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

AG#
RECEIVED

OCT 07 1991

DIVISION OF
OIL GAS & MINING

INSPECTION REPORT

PERMIT NO.: ACT/007/012 Inspection Date: September 26, 1991
 Permittee and/or Operators Name: Genwal Coal Co.
 Business Address: P.O. Box 766
 City: Wellington State: Utah Zip: 84542
 Mine Name: Wellington Prep Plant
 County: Carbon State: Utah
 Type of Mining Activity: Underground Surface Other XX
 Company Official (s): Jon Passic
 State Officials (s): Stephen J. Demczak
 Time of Inspection: 10:00 (X) a.m. () p.m. to 12:00 () a.m. (X) p.m.
 Partial XX Complete: Date of Last Inspection: August 27-28, 1991
 Weather Conditions: Warm, Low 80's
 Acreage: Permitted 1720 Disturbed 356 Regraded 1.5 Seeded 1.5
 Bonded 469 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	(X)
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	(X)
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES	()	()	()	()
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/012 INSPECTION DATE September 26, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Stream Channel Diversions -

The clear water diversions running south along the coal loadout facility was being repaired prior and during the time of inspection. The recent rain had caused some erosion of the embankments of the diversions from the undisturbed side. There were no breaches causing mixing of disturbed and undisturbed drainage.

4d. Other Sediment Control Measures -

The silt fences located on the north side of property by the topsoil pile and road access to the coal slurry ponds need maintenance in two (2) areas. The fences were performing correctly, but the recent storms have caused them to sag in places. The silt fences were reported to the operator for maintenance.

7. Coal Processing Waste -

The old U.S. Steel Coal refuge piles located on the north side of property may have depression on top of the pile. These depressions could possibly store water, but no water was observed during inspection. The pile may have to be reshaped in certain areas to prevent storage of water on the refuge pile. A closer investigation is required for verification.

Copy of report:

Mailed to: Genwal Coal Co.
Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)
Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39
Date: 10-1-91 