



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

TO: Daron Haddock, Permit Supervisor

FROM: Wayne H. Western, Reclamation Engineer *WHW*

DATE: April 6, 1993

RE: 2nd Installment Midterm Response, Castle Valley Resources, Wellington Prep Plant, ACT/007/012-93B, Folder #2, Carbon County, Utah

R645-301-512 Certification
R645-301-512.100 Cross Sections and Maps.

Original Deficiency:

Ten maps submitted with the original MPR have either not been properly signed or certified by a qualified registered professional engineer.

Permittee's Response:

All the above maps have been appropriately certified and labeled as required above with the exception of Map E9-3343 (2). A new (legible) drawing is being made of E9-3343 (2) and will be submitted to DOGM.

Analysis:

The Permittee did not include a legible copy of drawing E9-3343 (2), which is the loadout operation plan as requested in the original deficiency. He stated that a new copy is being made and will be submitted to DOGM.

In the original deficiency it was noted Map C9-1464, *Dryer Pond as Constructed*, had not been properly certified. Map C9-1285, *Auxiliary Pond*, was signed by Carl W. Winters, but not properly stamped. Copies or mention of Maps C9-1469 and C9-1285 were not included in the Permittee's deficiency response. The Permittee must supply the Division with certified copies of those maps in order to terminate the deficiency.

Remaining Deficiencies:

1. The Permittee must supply the Division with certified copies of Maps E9-3343 (2), C9-1469 and C9-1285.

R645-301-525 Subsidence

Original Deficiency:

The Applicant needs to address this section. If no subsidence will occur on site then the Applicant needs to state that in the Mining and Reclamation Plan.

Response:

This section has been addressed for the MRP.

The attached Section 5.35, p. 1 (3/27/93) should be inserted to the permit as Section 5.35, p.1 (3/27/93).

Analysis:

A copy of the Permittee's response has been placed in the MRP.

There has not been, nor is it anticipated that there will be, any underground mining at or near the site. Therefore, no mining induced subsidence is anticipated.

Deficiencies:

1. None.

R645-301-528.323 Burning and Burned Waste Utilization

Original Deficiency:

The Applicant will include a copy of the fire fighting plan as an appendix to the Mining and Reclamation Plan.

Page 3
ACT/007/012
April 6, 1993

Permittee's Response:

A fire fighting and evacuation plan had been previously written by the Operator. A copy is enclosed.

The attached Appendix K, (3/27/93) should be inserted to the permit as Appendix K in Volume III-C of the MRP.

Analysis:

The Permittee has supplied the Division with a copy of the fire fighting plan as requested.

Deficiencies:

1. None.

WELLING2.WHW