

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/012

DATE OF INSPECTION: July 15, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Diversions -

The diversions throughout the property were visibly inspected and had no signs of erosion or instability. There were no overtopping or bypassing of the diversions. The coal loadout facility had not seen rainfall during the month of June.

4b. Sediment Ponds -

The as-built drawings for the new sediment pond by the dryer building is in the process of being submitted to the Division. Work on the pond has been completed at the time of the inspection. The pond does have two spillways, an emergency and a principle.

4c. Other Sediment Control Measures -

Wellington Preparation Plant has several ASCA areas which consist of silt fences or straw bales. Several location straw bales were replaced since the last inspection. Silt fences were installed as designed and it appears that they would function correctly in a precipitation event.

8. Non-Coal Waste -

The operator will relocate a non-coal waste material storage area so that the drainage would enter into a sediment pond. The present site is loated in an ASCA area.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Castle Valley Resources, R. Jay Marshall
Mailed to: Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: July 20, 1994

Inspector's Signature and Number: Stephen J. Demczak #39
Stephen J. Demczak