

February 25, 1983

Inspection Memo to Coal File:

RE: Gordon Creek #2 Mine  
Beaver Creek Coal Company  
ACT/007/016, #7  
Carbon County, Utah

A partial inspection of the Gordon Creek #2 Mine was conducted by Sandy Pruitt and Scott Raymond on February 17, 1983. At the time of this inspection drainage from the loadout and parking lot was observed flowing down the road and off the permit area. To avoid a Notice of Violation it was requested that a water bar be constructed across the access to the loadout to convey disturbed area drainage to the sediment pond. This was completed immediately. A temporary conveyance of parking lot drainage to the cross culvert that drains into the sediment pond was also established. Scott Raymond explained that Beaver Creek had been aware of the problem and that gravel had been ordered for use in reestablishing the surface grades. According to Scott Raymond on the morning of February 18 permanent drainage control had been established by resurfacing the parking lot and loadout accesses with gravel. Due to time restraints a follow up inspection was not conducted.

SANDY PRUITT   
FIELD SPECIALIST

SP/lm

cc: Tom Ehmett, OSM  
Scott Raymond, BCCC  
Joe Helfrich, DOGM

Statistics:

See Genwal mine memo, dated February 25, 1983.