



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

RE  
7-6-87

0024

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

**INSPECTION REPORT**

INSPECTION DATE & TIME: 6/19/87; 8:00 am

Permittee and/or Operators Name: Beaver Creek Coal Company  
 Business Address: P.O. Box 1378 Price Utah 84501  
 Mine Name: Gordon Creek 2&7 Permit Number: ACT/007/016  
 Type of Mining Activity: Underground  Surface  Other   
 County: Carbon  
 Company Official (s): Dan Guy (Contacted 6/18/87, did not accompany on site  
 State Official(s): Kathryn Mutz, Rick Smith  
 Partial:  X Complete:  Date of Last Inspection: 5/13/87  
 Weather Conditions: Sunny and warm  
 Acreage: Permitted 2289 Disturbed 9 Regraded  Seeded  Bonded 9  
 Enforcement Action: None

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( X )	( )	( )	( X )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( X )	( )	( )	( X )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( X )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( X )	( )	( )	( X )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/016

DATE OF INSPECTION 6/19/87

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs at the entry to the mine were in place and in compliance with the approved permit.
- 4c. and 9. The water truck fill pond was not filling nor being used during our site visit. Water in the adjacent creek appeared clear. Large (greater than 10 inches) fish were swimming near the surface of the pond.
14. Having discussed a modification of BCCC's subsidence monitoring program with Dan Guy (6/18/87), we looked for subsidence monuments along the Beaver Creek drainage. No monuments could be located. Rick Smith, DOGM geologist will contact Dan Guy to further discuss monitoring and the location of monuments. No obvious adverse impacts of subsidence were noted on Beaver Creek or its riparian zone.
- 16b&d. We inspected straw bale installation along the mine access road. Bales were in good repair and functioning well. It appeared that the road had been maintained recently such that vehicle traffic was not degrading air quality.

Copy of this Report:

Mailed to: Donna Griffin (OSM), Dan Guy (BCCC)

Given to: Joe Helfrich, John Whitehead, Rick Smith

Inspectors Signature and Number:  #21 Date: 6/26/87