



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

ACT 1007/016

2

RICK

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

July 14, 1989

Mr. Dan Guy
Beaver Creek Coal Company
P.O. Box 1378
Price, UT 84501

Dear Dan:

We are writing you about following action required on the Gordon Creek #2, 7 & 8 coal permit renewal. It concerns noting three 18" culvert downspouts and an 8" perforated culvert on the map legend. They are shown on current maps, but legend is missing. Since a fourth 18" downspout is functional, you should use a different map symbol to differentiate between functional and non-functional culverts noted above.

The three downspouts were installed on the #7 mine coal conveyor belt drainage and conveyed water under the road. When major drainage changes were made and a half-round culvert installed immediately adjacent to the belt line, the three downspout inlets were covered and rather than tear up the road the culverts were to remain until final reclamation.

Documents needing revision - #7 Mine

Downspouts & Perforated Culvert - Drawing 7-7; Plate 3-1
Seep Plates 7-1, 3-7, and 3-7a

Since reclamation narrative 3.5.9 provides all culverts are to be removed, no additional narrative documentation is required. You should submit the revisions mentioned herein, consistent with previously established due dates.

Sincerely,

Wm. J. Malencik
Reclamation Specialist

WJM:jt