

**MOUNTAIN COAL COMPANY
2010 ANNUAL POND INSPECTION REPORT**

POND: Jacobs Pond

LOCATION: Gordon Creek 2/7/8


IMPOUNDMENTS	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	18" - 24" Water.
(5) Existing Storage Capacity	N/A
(6) Monitoring Procedures	Quarterly Inspection

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	N/A
(8) Sediment Cleanout Level (Elevation)	N/A
(9) Principle Spillway (Elevation)	N/A
(10) Emergency Spillway (Elevation)	N/A
(11) Existing Sediment Capacity (To Cleanout)	N/A

GENERAL	
(12) Comments/Recommendations	Stock/Wildlife Watering Pond. No Discharge. No Visible Inflow. Some Water Below Seep.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.



 (Signature)

08/26/10

 (Date)

