



OGMCOAL DNR <ogmcoal@utah.gov>

Gordon Creek 2, 7 & 8 Mines pond inspection 1st and 2nd qtrs

Chris Hansen <chansen@bowieresources.com>
To: Steve Demczak <stevedemczak@utah.gov>
Cc: "ogmcoal@utah.gov" <ogmcoal@utah.gov>

Tue, Jun 30, 2015 at 2:46 PM

Steve:

For your records I am attaching the Gordon Creek 2, 7 & 8 Jacob Pond Inspection reports for the first and second qtrs of 2015. Let me know if you have any questions.

Thanks,

Chris

2 attachments

 **1st Qtr Pond Inspection GC 2015.pdf**
27K

 **2nd Qrt Pond Inspection GC 2015.pdf**
246K

Jacob's Pond

Date: 3/23/2015
Time: 6:30

Inspector(s) Signature: *Judy A. Madala*

Quarterly Inspection Form

1st Quarter

	Yes	No	N/A	Action Required		Person Notified	Date Corrected	Comments/Remarks
				Yes/No	Yes/No			
Stability of Pond								
Pond stability/weakness	Stable			No				
Erosion/Stability of banks	Stable			No				
Vegetation problem around pond		X						
Hazardous Condition								
Any visible contaminants		X						
Hazardous condition observed		X						
Inlet Conditions								
Inlet functioning	X							
Culvert(s)/ditches functioning	X							
Principle & Emergency Spillways								
Water Discharging (rate)	No							
Pond water level	1/4 - 1/3 Full/ Ice Covered							
Spillway is clear of debris	Yes							
Oil skimmer			X					
Emergency spillway			X					
Primary spillway functioning	Yes							

Other Observations:

EarthFax Engineering Group, LLC

7324 South Union Park Avenue, Suite 100, Midvale, Utah 84047 • 801.561.1555 • FAX 801.561.1861



EarthFax

June 3, 2015

Mr. Chris Hansen
Director of Environmental Compliance and
Government Relations
Bowie Resource Partners, LLC
225 N 5th Street, Suite 900
Grand Junction, CO 81501

Subject: Inspection of Gordon Creek Sedimentation Pond

Dear Chris:

On June 2, 2015 I conducted an inspection of the sedimentation pond at the Gordon Creek No. 2/7/8 Mine. The pond (also known as Jacob's Pond) was impounding water at the time of my inspection but was not discharging. I observed no signs of instability in the embankment or the spillway, nor did I observe any sign of recent outflow from the pond.

I have attached two photographs of the pond area that I took during the inspection. These show the general condition of the pond at the time of my inspection.

It is my opinion that you may continue to use the pond in its current state.

Please contact me if you have any questions.

Sincerely,

Richard B. White, P.E.
President

Attachment



BRP

JUN 08 2015

Received

Emailed C. Hansen 6/8/15



Photo 1 - View of pond from downstream embankment



Photo 2 - View of spillway with pond in background