

7080  
0013



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

*get page*

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: December 20, 1989  
1:00 p.m. to 2:00 p.m.

Permittee and/or Operators Name: Beaver Creek Coal Company  
Business Address: P.O. Box 1378, Price, Utah 84501  
Mine Name: Gordon Creek #3 & #6 Permit Number: ACT/007/017  
Type of Mining Activity: Underground  Surface  Other   
County: Carbon  
Company Official (s): Dan Guy  
State Official(s): Henry Sauer  
Partial  Complete:  Date of Last Inspection: Nov. 2, 1989  
Weather Conditions: Clear and Cold  
Acreage: Permitted 668 Disturbed 34.4 Regraded 28 Seeded 28 Bonded 28  
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( X )	( )	( )	( X )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/017

DATE OF INSPECTION Dec. 20, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS
2. SIGNS AND MARKERS
3. TOPSOIL
4. HYDROLOGIC BALANCE
  - a. STREAM CHANNEL DIVERSIONS
  - b. DIVERSIONS
  - c. SEDIMENT PONDS AND IMPOUNDMENTS
  - d. OTHER SEDIMENT CONTROL MEASURES
  - e. SURFACE AND GROUNDWATER MONITORING
  - f. EFFLUENT LIMITATIONS
5. EXPLOSIVES
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL
- d. COAL PROCESSING WASTE
8. NONCOAL WASTE
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES
10. SLIDES AND OTHER DAMAGE
11. CONTEMPORANEOUS RECLAMATION
12. BACKFILLING AND GRADING
13. REVEGETATION
14. SUBSIDENCE CONTROL
15. CESSATION OF OPERATIONS
16. ROADS
  - a. CONSTRUCTION
  - b. DRAINAGE CONTROLS
  - c. SURFACING
  - d. MAINTENANCE
17. OTHER TRANSPORTATION FACILITIES
18. SUPPORT FACILITIES UTILITY INSTALLATIONS

: Copy of this Report:

Mailed to: John Kathman-OSM, and Dan Guy, BCCC

Given to: Joe Helfrich-DOGM

Inspectors Signature and Number: #32 Henry Sawyer Date: 1/2/90

INSPECTION REPORT  
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/017

DATE OF INSPECTION Dec. 20, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

Dan Guy (BCCC) accompanied the undersigned inspector on this partial state inspection of the mine site. Weather conditions were clear and cold.

2. Signs and Markers:

New permit signs have been installed at the front gate (permit boundary) and at the gate leading to the No. 3 mine.

4. Hydrologic Balance:

4(d) Other Sediment Control Measures

The silt fences throughout the site were inspected and found to be functioning well.

13 Revegetation

Supplemental hydroseeding and hydromulching has occurred this fall (1989). Seeding has been accomplished along the undisturbed diversion ditch along the access road to the No. 3 mine and on the slope above the No. 6 mine coal stockpile area.

djh  
AT43/68-70