

April 11, 1985

TO: Coal File, Inspection and Enforcement File
FROM: David Lof, Mining Field Specialist 
RE: Soldier Creek Coal Company, Soldier Canyon Mine,
ACT/007/018, #7, Carbon County, Utah

On March 21, 1985, I conducted a partial inspection at the above-mentioned mine site. I conducted the inspection after the operator's normal working hours, therefore, I was unaccompanied on the inspection.

Mine Identification Sign

During my February 21, 1985 complete inspection, I requested that the operator post a mine identification sign on the west side of the sewage lagoon ponds near the gate to the ponds. The operator did have signs posted on the fence warning people of the nature of the material in the lagoons and identifying the site as part of Soldier Creek's operations, but it did not have all the information required on a mine identification sign. At the time of this inspection, the operator had not installed a mine identification sign as requested.

Runoff Controls

The disturbed area runoff diversion around the mine site was properly maintained as was the cross-culvert inlet on the northwest side of the road.

Most, if not all snow cover, was gone from the mine site.

There was no discharge from the undisturbed bypass culvert at the time of the inspection.

btb

cc: Dave Spillman
Donna Griffin
Joe Helfrich

Statistics:

See Knight Mine memo dated April 11, 1985
0379R-18