

2-2-89
7/20
0001



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

gcl
SCL

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: January 10, 1989

1 p.m. to 3 p.m.

Permittee and/or Operators Name: Soldier Creek Coal Company
Business Address: P.O. Box I, Price, Utah 84501
Mine Name: Soldier Canyon Permit Number: ACT/007/018
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): David Spillman
State Official(s): David Darby
Partial: Complete: Date of Last Inspection: December 7, 1989
Weather Conditions: Clear and moderate
Acreage: Permitted 4348 Disturbed 12 Regraded Seeded Bonded
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	(X)
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	(X)	()	()	(X)
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/018

DATE OF INSPECTION January 10, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

There was approximately 2.5 feet of snow at the site. Access was limited to the mine yard and county road. No runoff was taking place due to the cold temperatures.

4f. Hydrologic Balance - Effluent Limitation

Soldier Creek Coal Company was discharging from their mine during the inspection. A water sample was collected in a one gallon plastic container. An examination of the sample revealed it to be clear with no oil film. Therefore, the sample was not submitted to the laboratory.

14. Subsidence Control

Using a combined mine and topographic map, I examined sites along the Soldier Canyon county road where mining has taken place under the road and stream. The road base was visible and revealed no fractures or disturbance.

Copy of this Report:

Mailed to: David Spillman, SCCC; Brian Smith, OSM;

Given to: Sue Linner, DOGM; Joe Helfrich, DOGM

Inspectors Signature and Number:  #18 Date: Jan. 31, 1989