

007/018 #2

0030

CONSULTANTS/ENGINEERS  
**HANSEN  
ALLEN  
& LUCE** inc

6771 SOUTH 900 EAST  
P.O. BOX 21146  
SALT LAKE CITY, UTAH 84121-0146  
(801) 566-5599

January 29, 1992

Mr. Daron Haddock  
Permit Supervisor  
Division of Oil, Gas and Mining  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203

Re: Soldier Creek Coal Company Permit Deficiencies

Dear Mr. Haddock:

In a letter dated January 14, 1992, from the Division to Soldier Creek Coal Company, permit deficiencies are identified. The purpose of this submittal is to address correction of the deficiencies associated with Map 760a. The disturbed area boundary has been drawn on this map. The proposed culvert on the pipeline road which was located outside of the disturbed area has been removed. The text associated with this culvert has been revised and is submitted herein for replacement in the permit application (page 7-144 revised). The inconsistent contour elevations have been corrected. The final step in preparation of the original of this map was using Kroy letters to label the contour elevations. The letters were simply placed incorrectly just before the map was copied for submittal. All mass balance calculations were completed before the Kroy labels were incorrectly applied to the map. Therefore, mass balance calculations and the resulting reclamation cost calculations are unaffected by this error.

The disturbed area boundary has also been drawn on Map 5.42a which is hereby resubmitted.

Enclosed are two copies each of Map 760a and Map 5.42a. Also there are two copies of revised page 7-144 for replacement in the permit application.

Thank you for your assistance in this matter.

Very truly yours,



Barry Barnum

**RECEIVED**

FEB 03 1992

DIVISION OF  
OIL GAS & MINING