

0007



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

0027
gch

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 17 September, 1992
9:30 a. m. to 11:20 a. m.

Permittee and/or Operator's Name: Soldier Creek Coal Company
Business Address: P. O. Box I, Price, Utah 84501
Mine Name: Soldier Creek Permit Number: ACT/007/018
Type of Mining Activity: Underground X Surface Other
County: Carbon
Company Official(s): Dave Spillman
State Officials(s): James D. Smith
Federal Official(s): none
Partial: X Complete: Date of last Inspection: 07 Aug, 1992
Weather Conditions: Sunny, low 70's, light breeze
Acreage: Permitted- 4905 Disturbed- 24 Regraded- Seeded- 1 Bonded- 24
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	(X)
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/018 DATE OF INSPECTION: 17 Sept, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

4.a. Stream Channel Diversions

The damage at the downstream side of the topsoil pile access road has been repaired. Rip-rap has been concreted into place at the upstream and downstream sides. The road surface has been stabilized with a concrete lined swale to carry excess runoff.


4.d. Other Sediment Control Measures

The erosion to the berm around the catch basin at the base of the road to fan site #3 has been repaired. There was dried mud in the bottom of the basin from a recent storm and the catch basin appears to have functioned as designed during this event.

Copy of this Report:

Mailed to: Brian Smith-OSM, Dave Spillman-Soldier Creek Coal Co.

Given to: Joe Helfrich-DOGM, Daron Haddock-DOGM

Inspector's Signature:  # 43 Date: 18 Sept, 1992