

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/018 DATE OF INSPECTION: January 22, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Diversions -

The diversions throughout the property were snow covered. The inspection was conducted during a snow storm. The disturbed snow was placed so that when melting occurs it will flow into the sediment pond.

4b. Sediment Ponds and Impoundments -

The sediment pond did contain a small amount of water. The pond slopes were snow covered; there was no erosion apparent, due to conditions.

16b. ROADS: Drainage Controls -

Roads were snow packed and no melting of snow was occurring.

19. AVS Check -

An AVS Check has been taken at the mine site with no new changes in ownership and control.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Soldier Creek Coal Company


Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: February 2, 1993

Inspector's Signature and Number: _____


Stephen J. Demdzak

#39