

October 1, 1985

TO: Coal File, Inspection and Enforcement Folder  
FROM: Tom Wright, Mining Field Specialist *TW*  
RE: Tower Resources Centennial Project, ACT/007/019, Folder #7,  
Carbon County, Utah

On September 19, I conducted a partial inspection of the Tower complex. Dave Wham, a new hydrologist for the Division, accompanied me. Alan Emmel of Tower was available and toured the site with us.

Improvements to the access road for the site were being made during the inspection. New road base was being applied to the surface below the canyon. Also, cleaning of a culvert had been underway during this week. This culvert, which crosses under the BLM road just south of a cattle guard at the mouth of the canyon, was plugged with sediment. As this is a public road, no enforcement action was warranted.

It appears that heavy rain had fallen on the site recently, as all sediment ponds contained water during this inspection. It appears that no discharge had occurred from these ponds, and all runoff from disturbed areas was properly contained.

The main canyon bypass for undisturbed runoff was clear on this date, and no flow was passing through the structure. It appeared that a slight flow through the structure has occurred since the last inspection.

No violations were noted on this inspection.

dd

cc: Alan Emmel  
Donna Griffin  
Ken May  
Joe Helfrich  
Sue Linner

Statistics: Vehicle: E x 49611, 805 miles  
Per diem: 1 person x 2 days, 6 hours = \$110.60

0342Q-16