



NO. N87-9-8-2

To the following Permittee or Operator:

Name Andalex Resources

Mine Centennial Project  Surface  Underground  Other

County Carbon State Utah Telephone 801/637-5385

Mailing Address P.O. Box 902 Price, Utah 84501

State Permit No. ACT/007/019

Ownership Category  State  Federal  Fee  Mixed

Date of inspection Sept. 18, 1987

Time of inspection 9:00  a.m.  p.m. to 1:00  a.m.  p.m.

Operator Name (other than Permittee) same as above

Mailing Address "

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is**  **is not**  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing Sept. 18, 1987 Time of service/ mailing 12:45  a.m.  p.m.

Michael Glasson Senior Geologist  
Permittee/Operator representative Title

Delivered at Site  
Signature

Holland Shepherd Reclamation Specialist  
Division of Oil, Gas & Mining representative Title

Holland Shepherd #9  
Signature Identification Number

SEE REVERSE SIDE

WHITE-DOGGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

0917



### NOTICE OF VIOLATION NO. N 87-9-8-2

Violation No. 1 of 2

Nature of violation

1) Failure to maintain drainage culverts in a manner which avoids plugging or collapse and erosion at inlets and outlets 2) Failure to maintain a diversion in a manner which prevents additional contributions of suspended solids to streamflow and runoff outside permit area.

Provisions of act, regulations or permit violated

- 1) UMC ~~817.43~~ 817.153 (c)(1)(ii)
- 2) UMC 817.43 (c)

Portion of operation to which notice applies

The disturbed area drainage ditch (DD-3 on plate #6) which runs from the fuel storage area to the Apex Mine portal pad. Two culvert inlets have been collapsed and the outlets are silted in. The culverts are located below the Shop/ Warehouse facility. The open ditch has become silted in in several locations.

Remedial action required (including any interim steps)

- 1) Repair ~~collapsed~~ collapsed culvert inlets and clean out outlets. ~~Be~~ ~~Be~~
- 2) Remove silt and redefine sections of the diversion that have become blocked. ~~Be~~ ~~Be~~

Abatement time (including interim steps)

- 1) Oct 2, 1987
- 2) Oct 2, 1987



### NOTICE OF VIOLATION NO. N 87-9-8-2

Violation No. 2 of 2

Nature of violation

Failure to protect stockpiled materials (topsoil) from water erosion and contaminants.

Provisions of act, regulations or permit violated

UMC 817.23

Portion of operation to which notice applies

The northeast toe of the substitute topsoil stockpile, or pond A side of the stockpile. Water from disturbed area drainage has breached the straw dike which protects the stockpile.

Remedial action required (including any interim steps)

- 1) Ensure diversion ditch DD-1 is constructed according to design specifications
- 2) Improve dike or berm protecting northeast toe.

Abatement time (including interim steps)

- 1) Oct. 30, 1987
- 2) Oct. 30, 1987