

0022



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

1/14/87

file

sdj

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 5-12-87
2:00 to 3:30 p.m.

Permittee and/or Operators Name: Andalex Resources
Business Address: P.O. Box 902 Price, Utah 84501
Mine Name: Centennial Project Permit Number: ACT/007/019
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): Michael Glasson
State Official(s): Holland Shepherd
Partial: Complete: Date of Last Inspection: 4-8-87
Weather Conditions: sunny, warm, no runoff at site
Acreage: Permitted 2360 Disturbed 31 Regraded 0 Seeded 0 Bonded 2360
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION 5-12-87

(Comments are Numbered to Correspond with Topics Listed Above)

3. Topsoil:

The operator has begun construction of a new machine shop facility in the area of the late substitute topsoil stockpile. The old substitute material has been scraped off the area, is being stockpiled, and will be used for fill material elsewhere on the property.

A new substitute topsoil stockpile has been established between ponds C and A. The operator has installed a topsoil sign and delineated the area with straw bales anchored with roof bolts.

Approval was made for the new topsoil area and removal of the old area in a letter from the Division, dated 4-23-87. According to the approval sediment pond A will no longer be used as a sediment pond facility since part of its east embankment is now topsoil material. Drainage which used to go to this pond will be rerouted to sediment pond C.

After my inspection of the new stockpile facility I requested the operator to increase the size of the berm on the west side of the pile, next to pond A. We agreed that earthen material could be used to heighten and better protect the topsoil material in this area. I also asked that the new diversion which channels water away from pond A, be deepened and widened. The diversion is located just north of the pond.

13. Revegetation:

The operator has seeded areas along the haul road which had been impacted by road construction last fall. The seeding was completed last week. The operator used a seed mix requested by the Division, and mulched areas seeded with a straw mulch.

I asked Mr. Glasson to seed one other area this spring that had been missed during this latest seeding. The area is located on the east side of the road just north of the undisturbed bypass culvert outlet.

Copy of this Report:

Mailed to: Michael Glasson, Donna Griffin
Given to: Joe Helfrich

Inspectors Signature and Number: Holland Shepherd #9 Date: 5-14-87