


0011



**ANDALEX**  
**RESOURCES, INC.**  
Tower Division

P.O. BOX 902  
PRICE, UTAH 84501  
PHONE (801) 637-5385  
TELEX 381 530 ANDALEX PRIC

A-9/007/019  
#2

June 20, 1988

**RECEIVED**  
JUN 22 1988

State of Utah  
Department of Natural Resources  
Division of Oil, Gas and Mining  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203

DIVISION OF  
OIL, GAS & MINING

Attention: Susan Linner

Dear Ms. Linner:

I have enclosed for your files a revised copy of our surface facilities as constructed plate. The reason for this is that an undisturbed drainage located above the lower Pinnacle Portals was originally shown as having been riprapped. It originally was; to be specific, it was lined with reinforced nylon and then riprapped. Over the years, various inspectors have visited the site and in discussions with Andalex have decided that although the soft bank was sloughing somewhat and covering the riprap it was slowly stabilizing. The division advised us to leave it alone but to maintain several straw dikes in the ditch. Recently inspector Darron Haddock pointed out that the map didn't agree with the on-site and wrote it as part of an NOV during an OSM oversight conducted approximately one month ago. Because of the Divisions observations regarding stability and Andalex's maintenance of the straw berms we would ask you to concur with this revised drawing which no longer shows any riprap.

Thank you very much.

Sincerely,

Michael W. Glasson  
Senior Geologist  
Western Operations

MWG/amr

Enclosure