

12-2-89
7040

0001



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Jed
SU

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

REVISED COPY

INSPECTION REPORT

INSPECTION DATE & TIME: December 20, 1988
8:45 a.m. - 11:00 a.m.

Permittee and/or Operators Name: Andalex Resources, Inc.
Business Address: P.O. Box 902 Price, Utah 84501
Mine Name: Centennial Project Permit Number: ACT/007/019
Type of Mining Activity: Underground Surface Other
County: Carbon State: Utah
Company Official(s): Mike Glasson
State Official(s): Daron Haddock
Partial: XX Complete: Date of Last Inspection: November 23, 1988
Weather Conditions: Partly cloudy, cold
Acreage: Permitted 2360 Disturbed 28 Regraded Seeded Bonded 30.7
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	(X)	()	()	(X)
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	(X)

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION December 20, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

4b. DIVERSIONS:

There is no water running anywhere on site and most of the mine diversions are in good condition. A couple of culvert inlets could use some maintenance, namely, the bypass culvert west of the Apex coal pile and the culvert along the road to the upper pinnacle portals, which diverts runoff into the mine.

8. NONCOAL WASTE:

The operator stores most noncoal waste in dumpsters which are taken to a landfill when full. The dumpster west of the Apex mine and the dumpster north of the new shop are both full and should be dumped. Rock dust bags are being piled next to the dumpsters. Mr. Glasson indicated that the contractor responsible for the dumpsters would be contacted and the trash hauled off.

18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS:

The mine power lines have been relocated to allow for the construction of a new mine in the Aberdeen seam. The power lines are now located on the east side of the mine road. The old poles have all been removed with the exception of two poles which will be removed by the operator when construction of the new mine begins. Disturbance as a result of the relocation appears to be minimal. One area effected by the power line move is the berm just south and east of sediment pond A. When installing guy wires, part of the berm was disturbed which might allow drainage from this area to run into the sediment pond. This is highly unlikely as the site, including the sediment pond, is dry. However, because the pond is not sized for this undisturbed drainage, the berm should be fortified. At the present time, this is a maintenance item which the operator will repair.

Copy of this Report:

Mailed to: Mike Glasson

Mailed to SLC for: Brian Smith, OSM Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: Daron R. Haddock #28 Date: 12/21/88