



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

August 18, 1988

TO: Sue Linner, Permit Supervisor

FROM: James S. Leatherwood, Reclamation Soils Specialist 

Re: Technical Deficiencies, Aberdeen Mine Development, Andalex Resources, ACT/007/019, Folder No.2, Carbon County, Utah

Aberdeen Mining and Reclamation Plan, received August 9, 1988, response to the Division's June 20, 1988 comments has been reviewed. Sections UMC 817.23 and UMC 817.48 cannot be considered technically adequate at this time. The following comments must be addressed before the plan can be considered technically adequate.

UMC 817.23 Topsoil: Storage - JSL

Page 114 refers to the wrong plates. Page 114 should refer to plate 7 instead of plate 6 and plate 38 instead of plate 37. Plate 38 does not indicate the volume of potential substitute topsoil material as discussed in the text on page 114. Page 114 must be clarified and Plate 38 must include the volume of material present for use as a potential suitable topsoil substitute.

UMC 817.48 Hydrologic Balance: Acid-Forming and Toxic-Forming Material - JSL

This section is inadequate at this time. The PAP states that samples have been submitted to a laboratory for analysis. However, the Division cannot make a determination of potential acid- or toxic-forming material until the requested information has been submitted and reviewed.

cc: D. Darby  
0534R89