



355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: June 22, 1988
9-11 a.m.

Permittee and/or Operators Name: Andalex Resources
Business Address: P.O. Box 902 Price, Utah 84501
Mine Name: Centennial Project Permit Number: ACT/007/019
Type of Mining Activity: Underground Surface Other
County: Carbon State: Utah
Company Official (s): Mike Glasson
State Official(s): Daron Haddock
Partial: Complete: Date of Last Inspection: May 19, 1988
Weather Conditions: Warm and sunny
Acreage: Permitted 2360 Disturbed 28 Regraded Seeded Bonded 30.7
Enforcement Action: Follow-up inspection to check abatement of NOV N88-28-3-1
which was terminated June 20, 1988

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	(X)
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION June 22, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

This inspection, a regular monthly inspection, was also conducted as a follow-up to determine abatement of NOV 88-28-3-1 which was terminated on June 20, 1988.

Mr. Glasson was not at the mine site but was contacted by phone. He gave his consent to the undersigned inspector to proceed with the inspection unattended.

1. PERMITS:

On June 16, 1988 the Utah Division of Oil, Gas and Mining approved a small area exemption concerning the mine office pad area relative to TDN 88-02-107-6 part 2 of 2.

The operator is currently working on a response to deficiencies recently encountered in the review of the operator's Aberdeen portal proposal.

4b. DIVERSIONS:

The site is dry with no water running in any of the diversions or sediment ponds. The diversions cited in NOV N88-28-3-1 were all checked with the following results.

1. The ditch south and west of the Apex truck loadout has been reconstructed.
2. The ditch south and west of the shop building has been reconstructed.
3. A new design plate for the diversion above the lower Pinnacle portals was sent to the Division on June 20, 1988 reflecting the current on-site conditions. This diversion is now protected by straw berms and vegetative cover rather than the riprap previously shown in the MRP.

It is the opinion of the undersigned inspector that work on these diversions appears to be adequate to abate the portion of the NOV dealing with diversions.

The 42-inch mine by-pass culvert has a dent in it approximately 20 feet from the outlet. The operator is aware of this and feels that during construction of the Aberdeen portals and sedimentation ponds this section of pipe can be cleaned and repaired.

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION June 22, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

A sediment level marker has been installed in pond C satisfying another part of NOV 88-28-3-1. The marker consists of a steel post with pink tape marking the clean out level. There is approximately 15 inches before the sediment level reaches the cleanout mark.

16c. ROAD SURFACING:

All of the paved roads on the mine site have recently (within the last two days) been resurfaced with oil and rock chip. The haul roads appear to be in good condition.

Copy of this Report:

Mailed to: Mike Glasson, Andalex

Mailed to SLC for: Brian Smith, DSM; Joe Helfrich, DOGM

Filed to: PFO

Daron R. Haddock

Inspectors Signature and Number: Daron Haddock #28 Date: June 23, 1988