



State of Utah  
 DEPARTMENT OF NATURAL RESOURCES  
 DIVISION OF OIL, GAS AND MINING

DRZ  
 Jch

Norman H. Bangarter  
 Governor  
 Dee C. Hansen  
 Executive Director  
 Dianne R. Nielson, Ph.D.  
 Division Director

355 West North Temple  
 3 Triad Center, Suite 350  
 Salt Lake City, Utah 84180-1203  
 801-538-5340

**INSPECTION REPORT**

INSPECTION DATE & TIME: Aug. 16, 1990  
10:30 a.m. to 12:00 p.m.

Permittee and/or Operators Name: Andalex Resources, Inc.  
 Business Address: Scofield Route, Helper, Utah 84526  
 Mine Name: Centennial Project Permit Number: ACT/007/019  
 Type of Mining Activity: Underground  Surface  Other   
 County: Carbon  
 Company Official (s): none.  
 State Official(s): Rick Summers  
 Partial:  Complete:  Date of Last Inspection: July 13, 1990  
 Weather Conditions: clear  
 Acreage: Permitted 3368 Disturbed 34 Regraded  Seeded  Bonded 34  
 Enforcement Action: none.

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( X )	( )	( )	( X )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)      Page 2 of 2

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION: 8/16/90

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

b. Diversions:

The culvert inlet to the old works has recently been cleaned and is functional. Maintenance at the diversion near the Pinnacle bath house noted during the previous inspection has been done. All other diversions are functional.

c. SEDIMENT PONDS AND IMPOUNDMENTS:

The operator has done some repair work for some minor rill development on the inslopes to pond A. All ponds were dry at the time of the inspection. No problems were observed.


e. Surface and Groundwater Monitoring:\

The operator has submitted NPDES reports for the site to the Division offices for the second quarter of 1990 (April through June). It was noted during the record review that 1990 water monitoring data for other sample sites and first quarter NPDES reports were not in the Division's monitoring data files. Mr. Glasson was contacted via telephone and he responded that he would forward copies of the data to the Division.

Copy of this Report:

Mailed to: Mike Glasson (Andalex) and Brian Smith (OSM-AFO)

Given to: Daron Haddock and Joe Helfrich - DOGM

Inspectors Signature and Number: #15  Date: 8/20/90